

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 11.05.2021
 Emailed : 05.06.2021, 12.20pm
 Date Survey : 11.05.2021

VEHICLE NO : SML 7583 X
 MODEL : KIA CERATO 1.6 A L
 WIP : 33259

Material	:	\$	<u>1,346.40</u>
Labour	:	\$	<u>2,010.00</u>
Sub-Total	:	\$	<u>3,356.40</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>3,056.40</u>
GST 7%	:	\$	<u>213.95</u>
Grand Total	:	\$	<u>3,270.35</u>
Finalise By/Date	:		<u>LOI / 05/06/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 18/05/2021	<table> <tr> <td>Cust No/Name</td><td>/TAN KOK SIONG (CHEN GUOXIONG)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SML7583X*KC17/ 03/06/2019</td></tr> <tr> <td>Date In/Mileage</td><td>18/05/2021/ 32391</td></tr> <tr> <td>Chassis/Package</td><td>KNAF1416MK5044407 /#</td></tr> <tr> <td>Engine No</td><td>G4FGKH737213</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A L S116</td></tr> <tr> <td>Colour/Trim</td><td>CR5 / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/TAN KOK SIONG (CHEN GUOXIONG)	Reg No/Reg Date	SML7583X*KC17/ 03/06/2019	Date In/Mileage	18/05/2021/ 32391	Chassis/Package	KNAF1416MK5044407 /#	Engine No	G4FGKH737213	Make/Model	KIA/CERATO 1.6 A L S116	Colour/Trim	CR5 / WK SATURN BLACK
Cust No/Name	/TAN KOK SIONG (CHEN GUOXIONG)														
Reg No/Reg Date	SML7583X*KC17/ 03/06/2019														
Date In/Mileage	18/05/2021/ 32391														
Chassis/Package	KNAF1416MK5044407 /#														
Engine No	G4FGKH737213														
Make/Model	KIA/CERATO 1.6 A L S116														
Colour/Trim	CR5 / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	05/06/2021/ 11:54	BLE	260 / AiTing	33259			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONTT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 400.00
E PNT98000 REPSRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 480.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT98000 RESPRAY BONNET & RH FRONT FENDER								960.00
X EXC EXCESS FOR OWN DAMAGE CLAIM								-300.00
X BEAM COMPLETE-FR BUMPER					1.00	? 497.00	20.00	397.60
X COVER-FR BUMPER					1.00	✓ 633.00	20.00	506.40
X GRILLE-FRONT BUMPER					1.00	✓ 262.00	20.00	209.60
X GRILLE ASSY-RADIATOR					1.00	✓ 223.00	20.00	178.40
X MOULDING-FRONT BUMPER,LH					1.00	✓ 36.00	20.00	28.80
X ORNAMENT-KIA NO.115					1.00	✓ 32.00	20.00	25.60
Z TEXT AIG OD CLAIM DOA : 11.05.21 SURVEYOR STEVE LKK 11.05.21 POLICY NO : 1900100389								

Pro Forma

Supp

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	1,346.40	Nett	3,056.40
Labour	1,990.00	7% GST on	213.95
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	3,270.35
Sundry/Others	-280.00		
Total(w/o GST)	3,056.40		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SML 7583 X

<u>Labour</u>		<u>Cost (\$)</u>
1	Respray on bonnet, RH front fender	960.00 ✓
Total Labour		----- 960.00
7% GST		67.20
Grand total		----- <u>\$ 1,027.20</u>

Thank You.

Yours Sincerely



LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 65651240

CAR NO: SML 7583XWIP: 33259 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Beam Complete-ER Bumper	? / SUPP		- BT	
2		? / SUPP			
3		? / SUPP			
4		? / SUPP			
5	RESPRAY BONNET \$ 480	? / SUPP			Done
6	RESPRAY RHF FENDER \$ 480	? / SUPP		-	19/5/21
7		? / SUPP		-	
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
19/5/21	Steve
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF MOUNT TO CELLETTE BENCH	
REMOVE AND INSTALL ENGINE	
REMOVE AND INSTALL DASHBAORD	
REMOVE & INSTALL FUEL TANK	
PHOTO UNDERCARRIAGE PARTS	

MODEL: CERATOSURVEYOR: STEVE



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



8/8

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
CLU	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.

M-E-K-01-00-0246

VCI Ver.

02.54

ECU Ver.

M-E-K-01-00-0187

OS Ver.

Android 10