

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0407/2021/HR
DATE : 7-May-21
WIP : 26615

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS NGUYEN THI THUY HANG
ADDRESS : 60 PHOENIX ROAD
SINGAPORE 668198
TELEPHONE : HP +65 87873588
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900114968-01
VEHICLE NO : **SML 3588 J**
MODEL CODE : Q8 3.0 TFSI qu 4MNOX
MODEL YEAR : 28/6/2019
ENGINE NO : DCB 067483
CHASSIS NO : WAUZZZF11KD015567
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-May-21
PLACE OF ACCIDENT : NEAR 17 TOH TUCK ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3588 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$ 480.00	X
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$ 480.00	X
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00	X
5	TO CARRY OUT WATER SEAPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	X
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00	600
SUB LABOUR CHARGES		\$ 4,620.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3588 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS. ✓ ✓	\$ 4,300.00	2200 ✓ 600 x 3 = 1800 Trim Arc = 200 x 2 = 400 2200
8	TO CARRY OUT DIAGNOSTIC CHECK. ✓ ✓	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 9,112.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3588 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR UPPER BUMPER <i>3 Dehd</i>	1	\$ 1,362.00	✓
2	REAR LOWER BUMPER	1	\$ 2,669.00	✓
3	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 170.00	X
4	REAR BUMPER TRIM - LEFT <i>Dehd</i>	1	\$ 86.00	✓
5	REAR BUMPER UPPER TRIM - CENTER <i>new</i>	1	\$ 129.00	X
6	REAR BUMPER LOWER TRIM - CENTER <i>ut</i>	1	\$ 423.00	✓
7	REAR BUMPER UPPER SPOILER <i>Dehd</i>	1	\$ 815.00	✓
8	REAR BUMPER CLOSING ELEMENT - LH <i>new</i>	1	\$ 95.00	X
9	REAR BUMPER CLOSING ELEMENT TRIM - LH <i>ut</i>	1	\$ 244.00	✓
10	REAR BUMPER LOWER SPOILER <i>?</i>	1	\$ 575.00	?
11	REAR BUMPER DIFFUSER <i>ut</i>	1	\$ 1,261.00	✓
12	REAR BOOT LID CONTROL UNIT <i>new</i>	1	\$ 411.00	X
13	REAR BOOT LID ANTHENA AERIAL	1	\$ 109.00	X
14	REAR BOOT LID ANTHENA AERIAL RETAINER <i>new</i>	1	\$ 19.00	X
15	REAR BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 1,417.00	X
16	REAR BUMPER SEAL - LH / RH <i>?</i>	2	\$ 28.00	?
17	REAR BUMPER HOLDING STRAP <i>?</i>	1	\$ 182.00	?
18	REAR BUMPER GUIDE SECTION - CENTER <i>new</i>	1	\$ 142.00	X
19	REAR BUMPER GUIDE SECTION - LEFT	1	\$ 67.00	X
20	REAR PARKING AID SENSOR <i>new</i>	1	\$ 244.00	X
SUB TOTAL SPARE PARTS		:	\$ 10,448.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3588]

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 14.00	X	
22	REAR BUMPER LIGHT REFLECTOR - LH <i>ambd</i>	1	\$ 136.00	✓	
23	OUTER TAIL LIGHT - LH <i>new</i>	1	\$ 1,455.00	X	
24	OUTER TAIL LIGHT TRIM - LH	1	\$ 44.00	X	
25	INNER TAIL LIGHT - CENTER <i>at</i>	1	\$ 3,354.00	✓	
26	INNER TAIL LIGHT TRIM - LH <i>new</i>	1	\$ 44.00	X	
27	REAR BOOT LID TAILGATE TRIM <i>new</i>	1	\$ 484.00	X	
28	REAR BOOT LID <i>Regis</i>	1	\$ 5,556.00	X	
29	REAR BOOT LID CLIP <i>new</i>	2	\$ 3.00	X	
30	REAR BOOT LID ADHESIVE <i>new</i>	1	\$ 19.00	X	
31	REAR FENDER PROTECTIVE FILM <i>new</i>	1	\$ 160.00	X	
32	REAR BOOT LID GASKET FLAP <i>new</i>	1	\$ 292.00	X	
33	REAR WINDOW <i>new</i>	1	\$ 1,174.00	X	
34	PRIMER <i>new</i>	1	\$ 20.00	X	
35	REAR BUMPER LONG SPOILER <i>new</i>	2	\$ 462.00	X	
36	"AUDI" EMBLEM <i>new</i>	1	\$ 138.00	✓	
37	"Q8" EMBLEM <i>new</i>	1	\$ 99.00	✓	
38	"QUATTRO" EMBLEM <i>new</i>	1	\$ 99.00	✓	
39	REAR WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 754.00	✓	
40	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$ 200.00	X	
41	SUNDRIES <i>?</i>		\$ 300.00	?	
TOTAL SPARE PARTS		:	\$ 25,255.00		
TOTAL LABOUR CHARGES		:	\$ 9,112.00		
GRAND TOTAL		:	\$ 34,367.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian
11/05/21


Not Authorised, 04 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD



JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT