

## RE: For DY CTP's Support, Pls] Procurement to seek LKK for Mechanical Inspection]

Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>

Tue 11/5/2021 5:04 PM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Raziz TAHAR (SPF) <Raziz\_TAHAR@spf.gov.sg>; NOORHIDAYAH ABDULLAH (SPF) <Noorhidayah\_ABDULLAH@spf.gov.sg>; Adrian LIM (SPF) <Adrian\_LIM@spf.gov.sg>; Kia Huat YEO (SPF) <YEO\_Kia\_Huat@spf.gov.sg>; Mohamed Yazid MOHAMMED YUSOFF (SPF) <Mohamed\_Yazid\_Mohammed\_Yusoff@spf.gov.sg>; Muhd Syakir ADANAN (SPF) <Muhd\_Syakir\_ADANAN@spf.gov.sg>; Intan Wulandari (SPF) <Intan\_Wulandari@spf.gov.sg>; Roizman POSARI (SPF) <Roizman\_POSARI@spf.gov.sg>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **22 vehicles** below. Those in **red** are deemed to be **urgent**:

- a. **Case IAFP-IB-20210511 - Mechanical Inspection of Motorcycle, JSY91 (TP/IP/10545/2021)**
- b. **Case IAFP-IB-20210511 - Mechanical Inspection of Lorry, GBD4265G (TP/IP/10545/2021)**

On 28 February 2021 (Sunday) at 3.47 p.m., the Involved Party (who was driving motor lorry GBD4265G) was travelling along AYE (Tuas), 20.3km when the motor lorry collided onto the Deceased, who was standing beside his motorcycle JSY91 on lane 3 of 3-lane road. As a result of the accident, the Deceased sustained head injuries and was conveyed to hospital where he subsequently succumbed to her injuries and was pronounced dead. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:**     **JSY91** - Rider (Deceased)  
   **GBD4265G** - Driver (Potential Defendant)

IO In-Charge: SIO Raziz

- c. **Case IAFP-IB-20210511 - Mechanical Inspection of Trailer, JPL6977 (TP/IP/15079/2021)**

On 24 March 2021 (Wednesday) at 06 p.m., the Involved Party (who was driving motor trailer JPL6977) was travelling along Woodlands Centre Road towards BKE(PIE) when the motor trailer collided onto the Deceased, who was crossing across the road from the Involved Party's right to left. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:**     **JPL6977** - Driver (Potential Defendant)

IO In-Charge: SIO Raziz

- d. **Case IAFP-IB-20210511 - Mechanical Inspection of Taxi, SHC2867S (TP/IP/ 19917/2021)**

On 20/04/2021 (Tuesday) 5.02 a.m., **(B1) SHC2867S** was stationary in a queue at the taxi pick-up point. He informed that there was a gap ahead of him and B1 press the accelerator pedal when suddenly the vehicle surged forward and collided onto the rear vehicle of a taxi ahead of him and causing the taxi surged forward and hit onto another taxi ahead in the queue. B1 claimed that his accelerator pedal was the cause of the accident. APD footage captured B1 was moving forward slowing and suddenly collided onto a taxi who was ahead of him. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:** SHC2867S - Driver (Involved Party)

IO In-Charge: IO Noorhidayah

e. **Case IAFP-IB-20210511 - Mechanical Inspection of Trailer, XE5590U/TRA9545S (TP/IP/16251/2021)**

- On 31 March 2021 sometime before 4.14 p.m., the Deceased was crossing the road across the zebra crossing along Penjuru Road x Penjuru Road when she was hit by the Accused's Trailer which was making a left turn from Penjuru Road into Penjuru Road from her right to left. Deceased sustained multiple injuries and was pronounced dead on the spot by attending SCDF paramedics at 4.38pm. A detailed mechanical inspection is required to rule out foul play.

- **Vehicles to be inspected:** XE5590U / TRA9515S - Driver (Potential Defendant)

IO In-Charge: SIO Adrian Lim

f. **Case IAFP-IB-20210511 - Mechanical Inspection of Police Car, QX660S (TP/IP/18939/2021)**

- On 15 April 2021 sometime before 4.41 p.m., the Potential Defendant was driving the Police car on lane 2 of 2 lanes road along Kovan Road with intention to make a left turn into Flower Road when he claimed that there was mechanical fault with the steering wheel, thus causing his vehicle to be unable to make the left turn and proceeded straight instead. A detailed mechanical inspection is required to determine if the steering wheel has any issues that may have caused the accident.

- **Vehicles to be inspected:** QX660S - Driver (Potential Defendant)

IO In-Charge: SIO Adrian Lim

g. **Case IAFP-IB-20210511 - Mechanical Inspection of Van, GBJ8758T (TP/IP/22459/2021)**

h. **Case IAFP-IB-20210511 - Mechanical Inspection of Bicycle (TP/IP/22459/2021)**

- On 4 May 2021 sometime before 10.18p.m., the accused was driving his motor van along Geylang Road and was making a right turn into Lorong 25 Geylang Road when the Cyclist came from Lorong 25 Geylang, against the flow of traffic and collided onto the right front portion of the motor van. Cyclist fell onto the road after the collision and sustained head injuries. Cyclist was conveyed to CGH where she succumbed to his injuries and was pronounced dead on the 7 May 2021 at 12.36pm. A detailed mechanical inspection is required to rule out foul play.

- **Vehicles to be inspected:** GBJ8758T - Driver (Potential Defendant)  
Bicycle - Pedal Cyclist (Deceased)

IO In-Charge: SIO Adrian Lim

i. **Case IAFP-IB-20210511 - Mechanical Inspection of Motorcycle, FBE5822L (TP/IP/18749/2021)**

- On 14 April 2021 at about 2340hrs, the rider of motorcycle, FBE5822L was travelling on lane 1 of 3-lane road along Jalan Boon Lay towards Jurong Pier Road when he lost control of his vehicle and skidded due to rear brake failure. A detailed mechanical inspection is required to rule out foul play.

- **Vehicles to be inspected:** FBE5822L - Rider (Potential Defendant)

j. Case IAFP-IB-20210511 - Mechanical Inspection of Trailer, XD2796T/TRB5972M (TP/IP/18921/2021)

k. Case IAFP-IB-20210511 - Mechanical Inspection of Motorcycle, FBG5353M (TP/IP/18921/2021)

l. Case IAFP-IB-20210511 - Mechanical Inspection of Motorcycle, FBM1410B (TP/IP/18921/2021)

On the 15/04/2021 at about 0743 hrs, motorcycle, FBG 5353 M, was travelling along Clementi Road in between lane 2 and lane 3 and collided onto the rear of motorcycle FBM 1410 B. On collision the rider of motorcycle FBG 5353 M fell on to path of trailer's rear left tyres and was run over. The rider of motorcycle FBG 5353 M Was sent to NUH where he succumbed to his injuries and was pronounced dead on the same day. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:** XD2796T/TRB5972M - Driver (Involved Party)  
FBG5353M - Rider (Deceased)  
FBM1410B - Rider (Involved Party)

IO In-Charge: SIO Yazid

m. Case IAFP-IB-20210511 - Mechanical Inspection of Motorcycle, FBN2822J (TP/IP/10473/2021)

n. Case IAFP-IB-20210511 - Mechanical Inspection of Van, GBG895Z (TP/IP/10473/2021)

On the 27 February 2021 sometime around 4.47 p.m., the van driver was travelling along Ang Mo Kio Avenue 3 and at the signalised T-Junction of Ang Mo Kio Avenue 4 proceeded to make a right turn when motorcycle that was travelling straight from the opposite direction collided onto the van. Due to the accident the rider of the motorcycle was sent to TTSH and on 2 March 2021 at 9.58 a.m., the Deceased succumbed to his injuries and was pronounced dead. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:** GBG895Z - Driver (Potential Defendant)  
FBN2822J - Rider (Deceased)

IO In-Charge: SIO Yazid

o. Case IAFP-IB-20210511 - Mechanical Inspection of Motorcycle, FBH9173J (TP/IP/16299/2021)

p. Case IAFP-IB-20210511 - Mechanical Inspection of Motorcar, SLC2528Z (TP/IP/16299/2021)

On 31/03/2020 at about 2007 hrs, the driver of motorcar was travelling on lane 3 of 3 lanes and the rider of motorcycle was riding on lane 1 of 3 lanes along Upper Changi Road. Both vehicle changed lanes to lane 2 and side swiped onto each other. As a result of the accident the rider and pillion were sent to CGH. The rider eventually passed away on the same day and the pillion was discharged. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:** SLC2528Z - Driver (Potential Defendant)  
FBH 9173 J - Rider (Deceased)

IO In-Charge: SIO Yazid

q. Case IAFP-IB-20210511 - Mechanical Inspection of Lorry, YM9808M (TP/IP/20677/2021)

On 24/04/2020 at about 0719 hrs, the driver of lorry claimed that he was travelling along Upper Bukit Timah Road towards Bukit Timah Road when there was a faulty on his brakes and steering wheel caused his lorry to skid and causing 9 of his passengers to be conveyed to the hospital. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:**     **YM9808M** - Driver (Potential Defendant)

IO In-Charge: IO Syakir

**r. Case IAFP-IB-20210511 - Mechanical Inspection of Tow-Truck, GT7606T (TP/IP/21603/2021)**

On 29 April 2021 at or about 12.44 p.m., the driver of tow-truck claimed that he was travelling along TPE(PIE), slip road into Loyang Avenue 1 when his tow-truck collided into 2 portion of metal guard railings and 1 signage pole. Driver claimed that there were brake faulty which caused the accident. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:**     **GT7606T** - Driver (Potential Defendant)

IO In-Charge: IO Syakir

**s. Case IAFP-IB-20210511 - Mechanical Inspection of Motorcar, SLE2371Y (TP/IP/37019/2020)**

On 29 August 2020 at about 06.45am, Police incident was created regarding an accident along Zion Rd. This is a case of a major hit and run RTA involving a pedestrian, 2 parked vehicles and private properties along Zion Rd in front of unit no 54. Vehicle was then left abandoned. CCTV from unit no 53 shows that subject who admitted to be driving the motor car, SLE2371Y was travelling at a speed along Zion Rd towards River Valley Rd, the vehicle was then seen mounting onto the left kerb before crashing onto outdoor seating area of unit 54 and onto a pillar, a pedestrian who was walking along the walkway and onto a parked car and van in front of unit 53. Driver claimed that when he was travelling along Zion Rd, the ABS system was suddenly activated, deflated airbags were deployed and steering wheel was locked. As driver could not control the vehicle, it caused him to lose control which caused the collision. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:**     **SLE2371Y** - Driver (Potential Defendant)

IO In-Charge: IO Intan

**t. Case IAFP-IB-20210511 - Mechanical Inspection of Trailer, XE6197R / TRD1512Z (TP/IP/19205/2021)**

**u. Case IAFP-IB-20210511 - Mechanical Inspection of Bicycle (TP/IP/19205/2021)**

On 16 April 2021 sometime before 8.23 p.m., the Defendant claimed that he was travelling along Jalan Buroh towards Pioneer Road on lane 2 of the 2-lane road and noticed the Deceased was on the left side of the road ahead of him hence he overtook the Deceased from the Deceased's right side. In the midst of overtaking, the Defendant noticed from his left mirror that the Deceased fell on the road. Upon seeing that, the Defendant stopped slightly ahead of the fallen Deceased and alighted from his vehicle to assist the Deceased. The Defendant claimed that he remained at scene for close to 30 minutes and left soon after he made a call to 995. The Deceased sustained multiple injuries and was conscious at the time of paramedic's arrival. However, on their way to National University Hospital, the Deceased had a sudden traumatic arrest and succumbed to his

injuries. The Deceased was pronounced dead in National University Hospital A & E at 10.15 p.m. by Dr Bryon Tee. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:**    **XE6197R / TRD1512Z** - Driver (Potential Defendant)  
**Bicycle** - Driver (Potential Defendant)

IO In-Charge: SIO Kamaliah

**v. Case IAFP-IB-20210511 - Mechanical Inspection of Motorcar, SLC7773R (TP/IP/22915/2021)**

On 7 May 2021 sometime before 2.40 a.m., the driver of motorcar, SLC7773R, was travelling along PIE towards Tuas to send his passenger home to Jurong. The driver claimed that before his motorcar lost control and had an accident, his motorcar was jerking and smoke emitted from the motorcar. The driver also informed that the brake was not working at that point of time. A detailed mechanical inspection is required to rule out foul play.

**Vehicle to be inspected:**    **SLC7773R** - Driver (Potential Defendant)

IO In-Charge: IO Roizman

2.        These request has been approved by my management.

3.        Thank you, Sirs.

cc:       Bryan, fyip

          SIO Raziz, IO Noorhidayah, SIO Adrian, SIO Kia Huat, SIO Yazid, IO Syakir, IO Intan & IO Roizman, as requested by you

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team

Traffic Police Department | Singapore Police Force

DID: (65) 6547 6435 | FAX: (65) 6547 6352



**Singapore Police Force**    **W** [police.gov.sg](https://police.gov.sg)    **FB** [fb.com/singaporepoliceforce](https://fb.com/singaporepoliceforce)    **IG**

[Instagram.com/singaporepoliceforce](https://Instagram.com/singaporepoliceforce)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."