

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Ho How Hon	
Ltd.	Reg No/Reg Date	SLE3556A / 19/07/201	
MOTOR CLAIM DEPARTMENT	Date In/Mileage		
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	KNAFX411MH5633248	
SINGAPORE 079120	Engine No	G4FGGH620859	
Contact No 64191000	Make/Model	KIA/FORTE K3 1.6 A EX BRQ	
		B4U GRAVITY BLUE / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	and the second
LAX00000	Credit	12/05/2021/ 08:57	QUK	289 / Patrick Lee		33267	
		Description of Good	s / Service	S	Qty	Unit Price Disc%	Amount
E PNT88000	EDT DIME			40		2,00%	2400.00
DEDATE OF	N EDT DOI	ER, HOOD, FRT LH FEN	DER				
E PNT98000	N FRI DUI	TH CHASSIS LEG & AFFI	ECTED AREA	AS			
	ON FRT BI	IMPER, HOOD, FRT LH I	CENDED DI	I A DILLAD			2100.00
BOTH FRT	CHASSIS	& AFFECTED AREAS	- ENDER, KI	A PILLAR,			
M SUNDRY	011110010	W THE COLD ANEAS					
APPLY BOI	DY SEALAN	IT ON AFFECTED AREAS					40.00
M SUNDRY							40.00
TO PERFOR	RM RUST P	REVENTION ON AFFECTE	D AREAS				40.00
A 54900099			П		7		30.00
CHECK WIF	RING & CH	ASSIS ELECTRICAL SYS	TEM 5	Imat orest	70		30.00
A 10028901	OUT DIAG	NOCTIO OUTOU	2011		1 (=	3	280.00
USING HI-	SCAN DDO	NOSTIC CHECK USING	HI-SCAN PR	OTEST [] [] CL (76	フ	
A WHEELALIGN		1531					
		erize Full Wheel Ali	anmont				120.00
A 33900099		or the fart whice Att	grilleric				
RENEW FRI	UNDERCA	RRIAGE DAMAGE					600.00
M SUNDRY							20.00
TO RENEW	FRT RH S	PORT RIM INCLUDING B	BALANCING				30.00
M SUNDRY							400.00
TO SUPPLY	RH FRT	SPORT RIM				1	100.00
M SUNDRY TO SUPPLY	DU EDT	TIDE					300.00
M SUNDRY	KII FKI	IIKE					
18 - 19 19 19 19 19 19 19 19 19 19 19 19 19	FRT NUM	BER PLATE WITH FRAME					50.00
M SUNDRY	. Alara Alara	DEN TENTE WITH THOME					
SUNDRIES							50.00
E PNT88000							100.00
REMOVE &	INSTALL I	RADIATOR & CONDENSER	TO FACIL	ITATE REPAIR			100.00
M SUNDRY							80.00
10 10P UP	A/C GAS	& CHECK A/C SYSTEM					30.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Ho How Hon
Ltd.	Reg No/Reg Date	SLE3556A / 19/07/201
MOTOR CLAIM DEPARTMENT	Date In/Mileage	
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	KNAFX411MH5633248
SINGAPORE 079120	Engine No	G4FGGH620859
Contact No 64191000	Make/Model	KIA/FORTE K3 1.6 A EX BRQ
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	12/05/2021/ 08:57	QUK	289 / Patrick Lee		33267		
F DNTOOOO		Description of Goods	s / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	1 7110 011							400.0
M CDILLE A	LLING ON	REPAIR WORK						
M GRILLE AS	SSY-KADIA	TOR			1.00	328.00	20.00	262.4
M COVER-FR		1.7051105 51 1-5			1.00	633.00	20.00	506.4
M MOULDING M LIP ASSY	-LKI RAK	LICENSE PLATE			1.00	18.00	20.00	14.4
	- FRONT BU	IMPER			1.00		20.00	44.0
M MOULDING	- FRONT BU	IMPER A/INTAKE			1.00	91.00	20.00	72.8
M LAMP ASSY					1.00	241.00	20.00	192.8
		MPER ENERGY			1.00	84.00	20.00	67.2
M RAIL ASSY					1.00	496.00		396.8
M DUCT ASSY	-AIR CUR	TAIN, LH	П		1.00		20.00	4.8
M AIR DUCT-	· FK ROWAF	R,LH	255	imai	1.00		20.00	26.4
STIFFNER-		WR			1.00	114.00		91.2
			96		1.00	13.00	20.00	10.4
4 GUARD ASS	Y-FRUNI	WHEEL, LH			1.00		20.00	76.0
PANEL-FEN					1.00	435.00	20.00	348.0
HINGE ASS					1.00	34.00	20.00	27.2
HINGE ASS		Н			1.00	34.00	20.00	27.2
					1.00	1384.00	20.00	1107.2
. G. GOOGITEITE					1.00	1330.00		1064.0
					1.00	380.00	20.00	304.0
					1.00	380.00	20.00	304.0
		T END MODULE			1.00	675.00	20.00	540.0
					1.00	280.00	20.00	224.0
M STRUT ASS P INSULATOR		DUT			1.00	280.00		224.0
					2.00	93.00	20.00	148.8
					2.00	42.00		67.2
<pre>1 GEAR ASSY 1 LINK-STAB</pre>		ū			1.00	832.00		665.6
		E DU			1.00	72.00		57.6
<pre>M KNUCKLE-F BEARING-F</pre>					1.00	350.00		280.0
HUB ASSY-		EL HOR			1.00	131.00		104.8
A LAMP ASSY					1.00	150.00		120.00
LAMP ASST	-neau, ch				1.00	1707.00	20.00	1365.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

Authorized signatory and company stamp

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Ho How Hon	
Ltd.	Reg No/Reg Date	SLE3556A / 19/07/201	
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16	Date In/Mileage	08/05/2021/ 99295	
AIG BUILDING	Chassis No	KNAFX411MH5633248	
SINGAPORE 079120	Engine No	G4FGGH620859	
Contact No 64191000	Make/Model	KIA/FORTE K3 1.6 A EX BRQ	
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	12/05/2021/ 08:57	QUK	289 / Patrick Lee		33267		
N ODMANS		Description of Goods	/ Services		Qty	Unit Price	Disc%	Amount
M ORNAMENT	-KIA NO.1	115			1.00	32.00	20.00	25.60
			n D	1				
		150	affi	ma	46			
			5)[4]		ILIE			
					de			
				EYOR NAME :				
			SURV					
			SURV	EYOR NAME :				
			SURV SURV DATE	EYOR NAME : EYOR SIGNATURE :				
			SURV SURV DATE	EYOR NAME : EYOR SIGNATURE : :				
			SURV SURV DATE	EYOR NAME : EYOR SIGNATURE : :				
			SURV SURV DATE	EYOR NAME : EYOR SIGNATURE : :				
Confirm & ac	ccepted by		SURV SURV DATE	EYOR NAME : EYOR SIGNATURE : :				
Confirm & ac	ccepted by		SURV SURV DATE	EYOR NAME : EYOR SIGNATURE : : RKS :				15,790.4 1105.3

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.