

TP AIG.
Xiao Chen.

SME7296L 2011 Dec
BMW 528i 1997cc
WBA XG32000C593475.

Front Bumper. torn	1546 ✓
Front Bumper Clips. new	50 ✓
Front Bumper Side Holder	78 x
Front Bumper Fog Lamp.	285 x
Front Bumper Sensor	250 x
Headlamp Ltl. ut	2210. -

Panel Beating.
Spray Painting
Wiring.

~~400~~ 200
~~400~~ 200
~~50~~ 30

To remove front bumper sensor.

~~100~~ 50.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

list: 3806

Len 10%: 3425.40

Labar: 480

total: 3905.40.

A/s: 3.1K.

02 Days.