



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104847

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 09/07/2021  
Reference CC4/FCI21005784/Ara3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SLB 5538E

Insured Veh. SG 1053D

Claim No. D21001482MFBP

Policy No. D-20096309MFBP

Accident Date 06/05/2021

Inspection Date 27/05/2021

Description	Total
Survey Inspection	175.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>175.00</b>
<b>GST (7%)</b>	<b>12.25</b>
<b>Grand Total</b>	<b>187.25</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21005784/Ara3q2	
			Date: 09/07/2021	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SG 1053D	Veh. Inspected	SLB 5538E	
Policy No.	D-20096309MFBP	Coverage (\$)	0.00	
Claim No.	D21001482MFBP	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	12/05/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA JAZZ	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMGK5850GX202174	Colour	BLUE	
Odometer	93056 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	MICHELIN	6 mm	
L/H Front Tyre	185/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	185/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	185/55 R16	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/05/2021	Inspection Date	27/05/2021	
Survey held at	EXCLUSIVE ENTERPRISE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 5538E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	556.00	556.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	26.00	26.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	518.30	-
1	TAILLAMP RH	NOT NECESSARY	302.00	-
	LESS 20% DISCOUNT		-280.46	-116.40
			1,121.84	465.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SEALANT (SN)	NOT NECESSARY	100.00	-
			150.00	30.00
	<b><u>LABOUR</u></b>			
	WIRE CHECK .		50.00	30.00
	R/R REAR REVERSE SENSOR .		80.00	50.00
	R/R REAR FENDER QUARTER GLASS .	NOT NECESSARY	120.00	-
	TUFF COAT.		100.00	30.00
	LABOUR .INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		500.00	250.00
	PAINTING .		500.00	400.00
			1,350.00	760.00
	<b>GRAND TOTAL</b>		<b>2,621.84</b>	<b>1,255.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,000.00</b>

Report Ref No. CC4/FCI21005784/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLB 5538E

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

