



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2202101

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 12/04/2022
Reference CC4/FCI21005785/Gea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBC 6231X
Insured Veh. SBS 3476S
Claim No. D21001501MFBP/1
Policy No. D-20096309MFBP
Accident Date 21/04/2021
Inspection Date 25/05/2021

Description	Total
Survey Inspection	386.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	386.00
GST (7%)	27.02
Grand Total	413.02

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21005785/Gea3q2	
			Date: 12/04/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBS 3476S	Veh. Inspected	FBC 6231X
	Policy No.	D-20096309MFBP	Coverage (\$)	0.00
	Claim No.	D21001501MFBP/1	Excess (\$)	0.00
	Assign From	ESTHER	Assign Date	12/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA T135	c.c	135
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	5YP006742	Colour	WHITE
	Odometer	44962 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	80/90-17	DUNLOP	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	90/80-17	DUNLOP	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/04/2021	Inspection Date	25/05/2021
	Survey held at	ENROUTE PERFORMANCE 61 WOODLANDS IND PARK E9 #01-03 SINGAPORE 757047 (Contact Person : SAM)		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 6231X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOX	CUT	230.00	165.00
1	RACK	NOT NECESSARY	190.00	-
1	EXHAUST	NOT NECESSARY	1,250.00	-
1	EXHAUST COVER	CUT	680.00	50.00
1	PILLION FOOT REST	NOT NECESSARY	62.00	-
1	RIDER FOOT REST	CUT	80.00	38.00
1	BALANCER	NOT NECESSARY	96.00	-
1	BRAKE LEVER	CUT	122.00	32.00
1	SET FRONT COVER	BROKEN	189.00	85.00
1	FONT SIDE COVER SET (R)	CUT	124.00	124.00
1	HEADLIGHT	NOT NECESSARY	264.00	-
1	FRONT SIGNAL LIGHTS	SCRATCHED	355.00	96.00
1	REAR COVER SET (R)	BROKEN	67.00	67.00
1	HANDLE BAR	BENT	169.00	98.00
1	CARPLATE FRONT	NECESSARY	65.00	15.00
1	FRONT MUDGUARD	CUT	96.00	78.00
1	SIDE MIRRORS	CUT	48.00	29.00
1	FOOT REST BRACKET	NOT NECESSARY	77.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	321.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	99.00	-
1	STEERING CONE BEARING	NOT NECESSARY	46.00	-
1	FORK ALIGNMENT	NOT NECESSARY	231.00	-
1	CHASIS ALIGNMENT	NOT NECESSARY	550.00	-
1	FRONT RIM ALIGNMENT	NOT NECESSARY	50.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	122.00	-
1	FRONT RIM BEARING	NOT NECESSARY	68.00	-
1	FORK OIL	NOT NECESSARY	53.00	-
1	FORK DUST COVER	NOT NECESSARY	66.00	-
1	FORK OIL SEAL	NOT NECESSARY	26.00	-
1	BRAKE CALIPER	NOT NECESSARY	247.00	-
1	BRAKE WIRE	NOT NECESSARY	36.00	-

Report Ref No. CC4/FCI21005785/Gea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING WHEEL CABLE	NOT NECESSARY	29.00	-
	LESS 10% DISCOUNT		-610.80	-87.70
			5,497.20	789.30
	LABOUR			
	BODY FRAME RE-ALIGNMENT .	NOT NECESSARY	800.00	-
	FORK RE-ALIGNMENT.	NOT NECESSARY	380.00	-
	FRONT RIM RE-ALIGNMENT .	NOT NECESSARY	380.00	-
	LABOUR TO DISMANTLE AND ASSEMBLE PARTS.		1,200.00	200.00
			2,760.00	200.00
GRAND TOTAL			8,257.20	989.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CC4/FCI21005785/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBC 6231X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBC 6231X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

