



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2105077

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 19/07/2021
Reference CC4/LPC21005787/Eps3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLR 1636Y
Insured Veh. YN 2323K
Claim No. 20/21/21/VC00/024561
Policy No. Z/20/VC00/107370
Accident Date 11/05/2021
Inspection Date 17/05/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21005787/Eps3q2 Date: 19/07/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2323K	Veh. Inspected	SLR 1636Y	
Policy No.	Z/20/VC00/107370	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024561	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	12/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	KIA FORTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNAFJ411MJ725374	Colour	GREY	
Odometer	71115 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/05/2021	Inspection Date	17/05/2021	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 1636Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRY (SN)	NECESSARY	20.00	20.00
1	COVER -RR BUMPER (SN)	DENTED	688.00	688.00
1	COVER -RR BUMPER ,CTR (SN)	CUT	315.00	315.00
1	BEAM -RR BUMPER (SN)	BROKEN	318.00	318.00
1	BRACKET -RR BEAM UPR MTG ,RH (SN)	NOT NECESSARY	3.00	-
1	BRACKET -RR BEAM UPR MTG (SN)	NOT NECESSARY	3.00	-
1	STAY -RR BUMPER RH (SN)	NOT NECESSARY	120.00	-
1	STAY -RR BUMPER LH (SN)	BENT	120.00	120.00
1	BRACKET -RR BUMPER SIDE MTG ,RH (SN)	NOT NECESSARY	29.00	-
1	BRACKET -RR BUMPER SIDE MTG ,LH (SN)	NOT NECESSARY	29.00	-
1	BRACKET -RR BEAM LWR MTG (SN)	NOT NECESSARY	5.00	-
1	BRACKET -RR BEAM LWR CTR (SN)	NOT NECESSARY	5.00	-
1	PANEL ASSY -TRUNK LID (SN)	DENTED	1,365.00	1,365.00
1	PANEL ASSY -BACK (SN)	TO REPAIR SEE LABOUR	324.00	-
1	LATCH ASSY -TRUNK LID (SN)	NOT NECESSARY	112.00	-
1	W/STRIP -TRUNK LID OPNG (SN)	NOT NECESSARY	100.00	-
1	TRIM -TRANSVERSE RR (SN)	CRUSHED	58.00	58.00
1	LAMP ASSY -REAR COMB INSIDE ,RH (SN)	BROKEN	242.00	242.00
1	LAMP ASSY-REAR COMBINATION ,RH (SN)	NOT NECESSARY	368.00	-
1	LAMP ASSY-REAR COMB INSIDE ,LH (SN)	BROKEN	242.00	242.00
1	LAMP ASSY -LICENSE PLATE ,LH (SN)	NOT NECESSARY	18.00	-
1	LAMP ASSY -LICENSE PLATE ,RH (SN)	NOT NECESSARY	18.00	-
1	LOGO ASSY-KIA SUB (SN)	NECESSARY	37.00	37.00
1	EMBLEM -CERATOR (SN)	NECESSARY	35.00	35.00
10	CLIPS (SN) (ADDITIONAL)	NECESSARY	20.00	20.00
1	EMBLEM K3 (SN) (ADDITIONAL)	NECESSARY	15.00	15.00
1	REAR NUMBER PLATE WITH FRAME (SN)	CUT	50.00	50.00
1	C&C LOGO (SN)	NECESSARY	40.00	40.00
			4,699.00	3,565.00

Report Ref No. CC4/LPC21005787/Eps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REPAIR REAR END PANEL. (ADDITIONAL)		200.00	200.00
	RESPRAY REAR END PANEL .(ADDITIONAL)		350.00	350.00
	RENEW REAR BUMPER ,BOOTLID ,REAR END PANEL.INCLUSIVE OF THE REPAIR OF PANEL ASSY - BACK.		2,750.00	1,280.00
	SPRAY PAINT FOR REAR BUMPER ,BOOTLID ,REAR END PANEL .		1,500.00	1,100.00
	REMOVE & INSTALL PARKING SENSOR .		100.00	80.00
	REMOVE & INSTALL REAR COMPARTMENT TRIMS.		300.00	120.00
	APPLY SEALANT FOR ACCIDENT PORTION .		80.00	40.00
	CHECK WIRING & ELECTRICAL SYSTEM.		30.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		280.00	280.00
			5,590.00	3,480.00
	GRAND TOTAL		10,289.00	7,045.00
RECOMMENDED COST OF REPAIRS				7,045.00

Report Ref No. CC4/LPC21005787/Eps3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 1636Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 1636Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

