

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address       | Owner Name & Vehicle Info                      |
|------------------------------|--|
| Tan Guangfan (chen Guangfan) | Cust No/Name /TAN GUANGFAN (CHEN GUANGFAN)     |
| BLK 259C PUNGGOL FIELD       | Reg No/Reg Date SLR1636Y / 02/08/201           |
| #15-57                       | Date In/Mileage / 0                            |
| SINGAPORE 823259             | Chassis No KNAFJ411MJ5725374                   |
| Contact No Mobile: 94301482  | Engine No G4FGGH636446                         |
|                              | Make/Model KIA/FORTE K3 1.6 A L 189            |
|                              | Colour/Trim MST METAL STREAM / WK SATURN BLACK |

| Account No   | Terms | Date/Time Printed | CSE | Operator     | WIP No |            |       |         |
|--|-------|-------------------|-----|--------------|--------|------------|-------|---------|
| CSM00081   | Cash  | 12/05/2021/ 10:33 |     | 442 / CocoLu | 33271  |            |       |         |
| Description of Goods / Services                      |       |                   |     |              | Qty    | Unit Price | Disc% | Amount  |
| E PNT88000   |       |                   |     |              |        |            |       | 2750.00 |
| RENEW REAR BUMPER, BOOTLID, REAR END PANEL           |       |                   |     |              |        |            |       |         |
| E PNT98000   |       |                   |     |              |        |            |       | 1500.00 |
| SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL |       |                   |     |              |        |            |       |         |
| E PNT88000   |       |                   |     |              |        |            |       | 100.00  |
| REMOVE & INSTALL PARKING SENSOR                      |       |                   |     |              |        |            |       |         |
| E PNT88000   |       |                   |     |              |        |            |       | 300.00  |
| REMOVE & INSTALL REAR COMPARTMENT TRIMS              |       |                   |     |              |        |            |       |         |
| M SUNDRY   |       |                   |     |              |        |            |       | 50.00   |
| REAR NUMBER PLATE WITH FRAME                         |       |                   |     |              |        |            |       |         |
| M SUNDRY   |       |                   |     |              |        |            |       | 80.00   |
| APPLY SEALANT FOR ACCIDENT PORTION                   |       |                   |     |              |        |            |       |         |
| M SUNDRY   |       |                   |     |              |        |            |       | 40.00   |
| C&C LOGO   |       |                   |     |              |        |            |       |         |
| A 90000001   |       |                   |     |              |        |            |       | 30.00   |
| CHECK WIRING & ELECTRICAL SYSTEM                     |       |                   |     |              |        |            |       |         |
| A 10028901   |       |                   |     |              |        |            |       | 280.00  |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST |       |                   |     |              |        |            |       |         |
| USING HI-SCAN PRO TEST                               |       |                   |     |              |        |            |       |         |
| M SUNDRY   |       |                   |     |              |        |            |       | 20.00   |
| Sundry   |       |                   |     |              |        |            |       |         |
| M COVER-RR BUMPER                                    |       |                   |     |              | 1.00   | 688.00     | 00.00 | 688.00  |
| M COVER-RR BUMPER,CTR                                |       |                   |     |              | 1.00   | 315.00     | 00.00 | 315.00  |
| M BEAM-RR BUMPER                                     |       |                   |     |              | 1.00   | 318.00     | 00.00 | 318.00  |
| M BRACKET-RR BEAM UPR MTG,RH                         |       |                   |     |              | 1.00   | 3.00       | 00.00 | 3.00    |
| M BRACKET-RR BEAM UPR MTG                            |       |                   |     |              | 1.00   | 3.00       | 00.00 | 3.00    |
| M STAY-RR BUMPER RH                                  |       |                   |     |              | 1.00   | 120.00     | 00.00 | 120.00  |
| M STAY-RR BUMPER LH                                  |       |                   |     |              | 1.00   | 120.00     | 00.00 | 120.00  |
| M BRACKET-RR BUMPER SIDE MTG,RH                      |       |                   |     |              | 1.00   | 29.00      | 00.00 | 29.00   |
| M BRACKET-RR BUMPER SIDE MTG,LH                      |       |                   |     |              | 1.00   | 29.00      | 00.00 | 29.00   |
| M BRACKET-RR BEAM LWR MTG                            |       |                   |     |              | 1.00   | 5.00       | 00.00 | 5.00    |
| M BRACKET-RR BEAM LWR,CTR                            |       |                   |     |              | 1.00   | 5.00       | 00.00 | 5.00    |
| M PANEL ASSY-TRUNK LID                               |       |                   |     |              | 1.00   | 1365.00    | 00.00 | 1365.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address       | Owner Name & Vehicle Info                      |
|------------------------------|--|
| Tan Guangfan (chen Guangfan) | Cust No/Name /TAN GUANGFAN (CHEN GUANGFAN)     |
| BLK 259C PUNGGOL FIELD       | Reg No/Reg Date SLR1636Y / 02/08/201           |
| #15-57                       | Date In/Mileage / 0                            |
| SINGAPORE 823259             | Chassis No KNAFJ411MJ5725374                   |
| Contact No Mobile: 94301482  | Engine No G4FGGH636446                         |
|                              | Make/Model KIA/FORTE K3 1.6 A L 189            |
|                              | Colour/Trim MST METAL STREAM / WK SATURN BLACK |

| Account No                      | Terms                         | Date/Time Printed | CSE | Operator     | WIP No     |       |        |
|---------------------------------|-------------------------------|-------------------|-----|--------------|------------|-------|--------|
| CSM00081                        | Cash                          | 12/05/2021/ 10:33 |     | 442 / CocoLu | 33271      |       |        |
| Description of Goods / Services |                               |                   |     | Qty          | Unit Price | Disc% | Amount |
| M                               | PANEL ASSY-BACK               |                   |     | 1.00         | 324.00     | 00.00 | 324.00 |
| M                               | LATCH ASSY-TRUNK LID          |                   |     | 1.00         | 112.00     | 00.00 | 112.00 |
| M                               | W/STRIP-TRUNK LID OPNG        |                   |     | 1.00         | 100.00     | 00.00 | 100.00 |
| M                               | TRIM-TRANSVERSE RR            |                   |     | 1.00         | 58.00      | 00.00 | 58.00  |
| M                               | LAMP ASSY-REAR COMB INSIDE,RH |                   |     | 1.00         | 242.00     | 00.00 | 242.00 |
| M                               | LAMP ASSY-REAR COMBINATION,RH |                   |     | 1.00         | 368.00     | 00.00 | 368.00 |
| M                               | LAMP ASSY-REAR COMB INSIDE,LH |                   |     | 1.00         | 242.00     | 00.00 | 242.00 |
| M                               | LAMP ASSY-LICENSE PLATE,LH    |                   |     | 1.00         | 18.00      | 00.00 | 18.00  |
| M                               | LAMP ASSY-LICENSE PLATE,RH    |                   |     | 1.00         | 18.00      | 00.00 | 18.00  |
| M                               | LOGO ASSY-KIA SUB             |                   |     | 1.00         | 37.00      | 00.00 | 37.00  |
| M                               | EMBLEM-CERATO                 |                   |     | 1.00         | 35.00      | 00.00 | 35.00  |

Estimate

Estimate

Confirm & accepted by

|               |         |           |
|---------------|---------|-----------|
| 7% GST on     | Nett    | 9,704.00  |
|               | 9704.00 | 679.28    |
| Total Payable |         | 10,383.28 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.