



Section A - Accident Details

Registration Number	SHC4470P
Case Reference Number	TAX/05/21/2029
Registration Date	12/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	ONG ENG JOO
Type of Accident	Side Swipe
Accident Date and Time	11/5/2021 2:38 PM
Accident Reported Date and Time	11/5/2021 4:46 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110903
Special Instruction to ARC, if any	TP /AIG - LKK
Prepared Date and Time	12/5/2021 11:20 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,854.00	\$780.00
Total Spare Part Cost	\$5,323.53	\$441.60
Total Other Cost	\$720.00	\$90.00
TOTAL COST	\$8,573.53	\$1,711.60
Lump Sum Total	\$8,550.00	\$1,700.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	14/05/2021 9:15 AM	12/05/2021 3:19 PM
Signature		
Remarks		L/S repair, take after spray

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2105-0334	Invoice Number	
Quotation Date	25.05.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00
TO RESPRAY RIM	\$180.00	\$30.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,854.00	\$780.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$10.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$720.00	\$90.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		5246247030	PAD, RR BUMPER, RH & LH , 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH , 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH , 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		5246147010	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given
		5245347010	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		5259147050	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given

R
X NN
X NN
X NN
X NN
X NN
X NN
X NN
X NN
X NN
X NN

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/05/2021

User ID : PohSuan

		5256547900	FILLER, RR BUMPER , RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X NN
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓ NEC
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓ NEC
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X NN
		5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X NN
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X NN
		7585047910	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$576.00	25.00	\$432.00	Replace	Replace	✓ BR
		6700347210	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair	R
		6875020122	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given	X NN
		6877052031	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given	X NN
		8572047150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Not Given	X NN
		6980347020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$200.70	0.00	\$0.00	Replace	Not Given	X NN
		6921147021A1	DOOR OUTER HANDLE REAR , RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X NN
		8215347250	WIRE, REAR DOOR, RH	0.00	\$206.70	0.00	\$0.00	Replace	Not Given	X NN
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	R
		6556547010	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$33.70	0.00	\$0.00	Replace	Not Given	X NN
		6563747060	LINER, REAR FENDER , RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X NN
		4261147450	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	R
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X NN
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X NN
Total					\$8,494.94		\$552.00			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

552.00
-20%
441.60
+ 400.00
+ 870.00
1,711.60

L/S \$1,700/-