

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 31815

Your Reference : GA567846

Accident Date : 11-May-2021

Date : 15-May-2021

Our<sup>✓</sup> Ref : 021191 / SANDRA

PAGE : 1

AXA INSURANCE PRIVATE LIMITED

8 SHENTON WAY

#24-01 AXA TOWER

Singapore 068811

ESTIMATED COST OF REPAIR FOR BMW 420I M SPORT(1997cc)(2015) SMY4982D

1 pc	n/s front door		X 900.00 c	Serviceable
1 pc	n/s front door lower seal big	BURNT	✓ 120.00 c	
1 pc	n/s front door lower seal small	BURNT	✓ 40.00 c	
1 pc	n/s front door outer weather-strip		X 115.00 c	Serviceable
1 pc	n/s front door outer mirror triangle seal	BURNT	✓ 18.00 c	
1 pc	n/s front door outer moulding		X 195.00 c	Serviceable
1 pc	n/s front door A pillar seal	BURNT	✓ 80.00 c	
1 pc	n/s front door mirror base outside seal		? 130.00 c	
1 pc	n/s front door corner moulding		? 40.00 c	
1 pc	n/s front door inner vertical seal		? 55.00 c	
1 pc	n/s front door inner sound insulation - top		? 100.00 c	
1 pc	n/s front door inner sound insulation - lower		? 100.00 c	
1 pc	n/s front door inner pull handle	BURNT	✓ 130.00 c	
1 pc	n/s front door inner handle accent moulding		? 175.00 c	
1 pc	n/s front door arm rest in leather	BURNT	✓ 350.00 c	
1 pc	n/s front door inner pull handle aluminium cover		? 265.00 c	

Con't Page 2 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : GA567846

Our Ref : 021191

Page : 2

No. : 31815

1 pc	n/s front door inner pull handle base support	BURNT	✓ 125.00 c	
1 pc	n/s front door wireharness		✓ 275.00 c	BURNT
1 pc	n/s front door glass		? 290.00 c	
1 pc	n/s front door twitter speaker	BURNT	✓ 185.00 c	
1 pc	n/s front door regulator		× 250.00 c	Serviceable
1 pc	n/s front door regulator motor	Serviceable	× 250.00 c	
1 pc	n/s front door sensor		? 135.00 c	
1 pc	n/s front door speaker (main)		✓ 240.00 c	BURNT
1 pc	n/s front door lock cable		? 60.00 c	
1 pc	n/s front door power window switch panel		? 80.00 c	
1 pc	n/s front door inner trim-board	BURNT	✓ 1,600.00 c	
1 pc	n/s front door LED module for armrest	BURNT	✓ 55.00 c	
1 pc	n/s front door LED module		? 45.00 c	
1 pc	n/s front door optical conductor upper left		? 60.00 c	
1 pc	n/s front door inner handle lighting		? 60.00 c	

		6,523.00	
Add	10% :	652.30	
			7,175.30

1 pc	n/s front door glass solar film	?	180.00	sn
------	---------------------------------	---	--------	----

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

180 400.00

To remove door's fittings

60 80.00

Con't Page 3 ...

Press any key to continue...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : GA567846

Our Ref : 021191

Page : 3

No. : 31815

To putty and respray on affected  
portions.

400 500.00

Total : S\$ 8,335.30

Singapore Dollars EIGHT THOUSAND THREE HUNDRED  
THIRTY FIVE AND CENTS THIRTY Only

4days

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul> <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>
---