



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 21.28699

Date: 14th June 2021

Our Ref : CS3/ASM21001924/Gtf3e2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMD 1603D
INSURED VEHICLE: SFU 1816A
ACCIDENT DATE: 08/02/2021

We thank you for your instruction on 14/05/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMD 1603D from M/s United Appraisal And Management Pte Ltd.
- b) Singapore Accident Statement of Vehicles SMD 1603D and SFU 1816A.
- c) Final Repair Bill of SMD 1603D from M/s Palladium Auto Solutions.
- d) Colour damaged vehicle photographs of SMD 1603D.

Pre-Repair Inspection Date : 09/02/2021 at M/s 160 Sin Ming Drive #07-11, Repairer: Palladium Auto Solutions Pte Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMD 1603D
Make & Model	: Toyota Alphard 7-Seater 2.5S CVT
Year of Registration	: Black
Chassis Number	: AGH300190070
Engine Capacity	: 2493 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.