



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Pang Cheng Chin Reg No/Reg Date SLA3998D / 29/02/201 Date In/Mileage / 0 Chassis No KNAFX411MG5579600 Engine No G4FGFH609748 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	14/05/2021/ 09:35	QUK	289 / Patrick Lee Kevin	33327			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT ¹ RH DOOR, REAR ¹ RH DOOR, REAR RH ³ QUARTER PANEL, REAR ¹ BUMPER & AFFECTED AREAS					4 X 420			1600.00
E PNT98000 SPRAY ON FRT ¹ RH DOOR, REAR ¹ RH DOOR, REAR RH ¹ QUARTER PANEL, REAR ¹ BUMPER					4 X 350			1400.00
E PNT88000 REMOVE & INSTALL PARKING ASSIST SENSOR								80 120.00
E PNT88000 REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR								240.00
M SUNDRY TO APPLY WINDSCREEN SEALANT								80.00
E PNT88000 TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL								120.00
E PNT88000 TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL								120.00
E PNT88000 TO REMOVE REAR CABIN COMPARTMENT TO FACILITATE REPAIR (photo)								? 80.00
M SUNDRY TO APPLY BODY SEALANT ON AFFECTED AREAS								40 120.00
M SUNDRY TO PERFORM RUST PREVENTION								40 120.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM								30 120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120 280.00
M SUNDRY SUNDRIES								20 50.00
M PANEL ASSY-FRONT DOOR, RH					1.00	1542.00	20.00	1233.60
M PANEL ASSY-REAR DOOR, RH					1.00	1361.00	20.00	1088.80
M COVER-RR BUMPER					1.00	791.00	20.00	632.80
M BRACKET-RR BUMPER SIDE MTG, RH					1.00	33.00	20.00	26.40
M LAMP ASSY-REAR COMBINATION, RH					1.00	843.00	20.00	674.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Pang Cheng Chin Reg No/Reg Date SLA3998D / 29/02/201 Date In/Mileage / 0 Chassis No KNAFX411MG5579600 Engine No G4FGFH609748 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	14/05/2021/ 09:35	QUK	289 / Patrick Lee	33327

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL ASSY-QUARTER OUTER, RH / 00	1.00	1213.00	20.00	970.40
M FILM-ANTI CHIPPG RH / n/c	1.00	27.00	20.00	21.60
M BLACK TAPE-FR DR FRAME UPR, RH / n/c	1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FRAME UPR, RH / n/c	1.00	11.00	20.00	8.80
M BLACK TAPE-FR DR RR, RH / n/c	1.00	12.00	20.00	9.60
M TAPE-RR DR FRAME BLACK RR, RH / n/c	1.00	8.00	20.00	6.40
M GUARD ASSY-REAR WHEEL, RH / CRW	1.00	75.00	20.00	60.00
M W/STRIP ASSY-FR DR BELT O/S RH / ?	1.00	58.00	20.00	46.40
M W/STRIP ASSY-FR DR SIDE RH / ?	1.00	122.00	20.00	97.60
M W/STRIP ASSY-RR DR BELT O/S RH / ?	1.00	89.00	20.00	71.20
M W/STRIP ASSY-RR DR SIDE RH / ?	1.00	114.00	20.00	91.20
M PAD-WINDSHIELD GLASS / n/c	1.00	2.00	20.00	12.80
M GLASS ASSY-REAR WINDOW / n/c	1.00	534.00	20.00	427.20
M MOULDING-REAR WINDOW GLASS / n/c	1.00	27.00	20.00	21.60
M STOPPER-RR WINDOW GLASS / n/c	2.00	4.00	20.00	6.40

Rear RH RIM / CUT

SURVEYOR NAME: Steve CLKK 17/5/21, 4.00p

SURVEYOR SIGNATURE: 00-AL AL

DATE: EXPRS - ?

REMARKS: PIP

My BL Sy

11 days

Confirm & accepted by	LKK Auto Consultants hence notify the Repairer of the following:	Nett	9,967.60
	• To display damaged part(s) during resurvey	7% GST on	9967.60
	• Parts prices are subject to confirmation		697.73
	• Third party survey is on a "Without Prejudice" basis	Total Payable	10,665.33
	• No illegal modification(s) is allowed		
	• Supplementary item(s) must be resurveyed and		
Authorized signatory and company stamp			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.