



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Pang Cheng Chin Reg No/Reg Date SLA3998D / 29/02/201 Date In/Mileage / 0 Chassis No KNAFX411MG5579600 Engine No G4FGFH609748 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	14/05/2021/ 09:35	QUK	289 / Patrick Lee Kevin	33327			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1600.00 ✓
REPLACE FRT ¹ RH DOOR, REAR ¹ RH DOOR, REAR RH ³ QUARTER PANEL, REAR ¹ BUMPER & AFFECTED AREAS					4 X	400		
E PNT98000								1400.00 ✓
SPRAY ON FRT ¹ RH DOOR, REAR ¹ RH DOOR, REAR RH ¹ QUARTER PANEL, REAR ¹ BUMPER					4 X	350		
E PNT88000								80 120.00
REMOVE & INSTALL PARKING ASSIST SENSOR								240.00 ✓
E PNT88000								80.00 ✓
REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR								
M SUNDRY								120.00 ✓
TO APPLY WINDSCREEN SEALANT								120.00 ✓
E PNT88000								120.00 ✓
TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL								80.00 ✓
E PNT88000								120.00 ✓
TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL								
E PNT88000								40 120.00
TO REMOVE REAR CABIN COMPARTMENT TO FACILITATE REPAIR (photo)								40 120.00
M SUNDRY								40 120.00
TO APPLY BODY SEALANT ON AFFECTED AREAS								30 120.00 ✓
M SUNDRY								120.00 ✓
TO PERFORM RUST PREVENTION								120 280.00 ✓
A 54900099								70 50.00
CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
SUNDRIES								
M PANEL ASSY-FRONT DOOR,RH					1.00	1542.00	20.00	1233.60 ✓
M PANEL ASSY-REAR DOOR,RH					1.00	1361.00	20.00	1088.80 ✓
M COVER-RR BUMPER					1.00	791.00	20.00	632.80 ✓
M BRACKET-RR BUMPER SIDE MTG,RH					1.00	33.00	20.00	26.40 ✓
M LAMP ASSY-REAR COMBINATION,RH					1.00	843.00	20.00	674.40 ✓

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 ATG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Pang Cheng Chin Reg No/Reg Date SLA3998D / 29/02/201 Date In/Mileage / 0 Chassis No KNAFX411MG5579600 Engine No G4FGFH609748 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	14/05/2021/ 09:35	QUK	289 / Patrick Lee	33327			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL ASSY-QUARTER OUTER, RH	✓	00		1.00	1213.00	20.00	970.40
M	FILM-ANTI CHIPPG RH	✓	APC		1.00	27.00	20.00	21.60
M	BLACK TAPE-FR DR FRAME UPR, RH	✓	APC		1.00	13.00	20.00	10.40
M	BLACK TAPE-RR DR FRAME UPR, RH	✓	APC		1.00	11.00	20.00	8.80
M	BLACK TAPE-FR DR RR, RH	✓	APC		1.00	12.00	20.00	9.60
M	TAPE-RR DR FRAME BLACK RR, RH	✓	APC		1.00	8.00	20.00	6.40
M	GUARD ASSY-REAR WHEEL, RH	✓	CRH	X KIN	1.00	75.00	20.00	60.00
M	W/STRIP ASSY-FR DR BELT O/S RH	✓	X KIN		1.00	58.00	20.00	46.40
M	W/STRIP ASSY-FR DR SIDE RH	✓	X KIN		1.00	122.00	20.00	97.60
M	W/STRIP ASSY-RR DR BELT O/S RH	✓	BT		1.00	89.00	20.00	71.20
M	W/STRIP ASSY-RR DR SIDE RH	✓	X KIN		1.00	114.00	20.00	91.20
M	PAD-WINDSHIELD GLASS	X	APC	X KIN	3.00	2.00	20.00	12.80
M	GLASS ASSY-REAR WINDOW	X	APC	X KIN	1.00	534.00	20.00	427.20
M	MOULDING-REAR WINDOW GLASS	X	APC	X KIN	1.00	27.00	20.00	21.60
M	STOPPER-RR WINDOW GLASS	X	APC	X KIN	2.00	4.00	20.00	6.40

Rear RH RIM / CHT

SURVEYOR NAME: Steve CLKK) 17/5/21, 4.00p
SURVEYOR SIGNATURE: 00-AL AL
DATE: EXPRS -?
REMARKS: PIP
My BL Sy
11 days

LKK Auto Consultants hence notify

the Repairer of the following:

Confirm & accepted by

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

7% GST on
Total Payable
9,967.60
9967.60
10,665.33

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.