



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Pang Cheng Chin
	Reg No/Reg Date	SLA3998D / 29/02/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MG5579600
	Engine No	G4FGFH609748
	Make/Model	KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim	D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	14/05/2021/ 09:35	QUK	289 / Patrick Lee Kevin	33327		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT RH DOOR, REAR RH DOOR, REAR RH QUARTER PANEL, REAR BUMPER & AFFECTED AREAS							1600.00
E PNT98000 SPRAY ON FRT RH DOOR, REAR RH DOOR, REAR RH QUARTER PANEL, REAR BUMPER							1400.00
E PNT88000 REMOVE & INSTALL PARKING ASSIST SENSOR							120.00
E PNT88000 REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR							240.00
M SUNDRY TO APPLY WINDSCREEN SEALANT							80.00
E PNT88000 TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL							120.00
E PNT88000 TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL							120.00
E PNT88000 TO REMOVE REAR CABIN COMPARTMENT TO FACILITATE REPAIR							80.00
M SUNDRY TO APPLY BODY SEALANT ON AFFECTED AREAS							120.00
M SUNDRY TO PERFORM RUST PREVENTION							120.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM							120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							280.00
M SUNDRY SUNDRIES							50.00
M	PANEL ASSY-FRONT DOOR,RH			1.00	1542.00	20.00	1233.60
M	PANEL ASSY-REAR DOOR,RH			1.00	1361.00	20.00	1088.80
M	COVER-RR BUMPER			1.00	791.00	20.00	632.80
M	BRACKET-RR BUMPER SIDE MTG,RH			1.00	33.00	20.00	26.40
M	LAMP ASSY-REAR COMBINATION,RH			1.00	843.00	20.00	674.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Pang Cheng Chin
	Reg No/Reg Date	SLA3998D / 29/02/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MG5579600
	Engine No	G4FGFH609748
	Make/Model	KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim	D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	14/05/2021/ 09:35	QUK	289 / Patrick Lee	33327

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL ASSY-QUARTER OUTER,RH	1.00	1213.00	20.00	970.40
M FILM-ANTI CHIPPG RH	1.00	27.00	20.00	21.60
M BLACK TAPE-FR DR FRAME UPR,RH	1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FRAME UPR,RH	1.00	11.00	20.00	8.80
M BLACK TAPE-FR DR RR,RH	1.00	12.00	20.00	9.60
M TAPE-RR DR FRAME BLACK RR,RH	1.00	8.00	20.00	6.40
M GUARD ASSY-REAR WHEEL,RH	1.00	75.00	20.00	60.00
M W/STRIP ASSY-FR DR BELT O/S RH	1.00	58.00	20.00	46.40
M W/STRIP ASSY-FR DR SIDE RH	1.00	122.00	20.00	97.60
M W/STRIP ASSY-RR DR BELT O/S RH	1.00	89.00	20.00	71.20
M W/STRIP ASSY-RR DR SIDE RH	1.00	114.00	20.00	91.20
M PAD-WINDSHIELD GLASS	8.00	2.00	20.00	12.80
M GLASS ASSY-REAR WINDOW	1.00	534.00	20.00	427.20
M MOULDING-REAR WINDOW GLASS	1.00	27.00	20.00	21.60
M STOPPER-RR WINDOW GLASS	2.00	4.00	20.00	6.40

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

Confirm & accepted by

	Nett	9,967.60
7% GST on	9967.60	697.73
Total Payable		10,665.33

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.