



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS3/GAI21004178/Gqf3e2-1 Date: 14/06/2021 Code: GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YQ 530B	Veh. Inspected	SJM 5327M
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003985	Excess (\$)	0.00
Assign From	ELIZABETH CHEW	Assign Date	14/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA FIT 1.3G	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GE61094260	Colour	RED
Odometer	181299 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	29/03/2021	Inspection Date	01/04/2021
Survey held at	BLK 2 KAKI BUKIT AVE 2 #02-25 KAKI BUKIT AUTO-HUB		
Repairer	H S AUTOMOTIVE SERVICES		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	