



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 05/05/2021

ESTIMATE

NO : QUOT202105-000029(00)

DATE : 14/05/2021

POLICY NO : 999995580

VEH REG NO : SLL1400S

MAKE/MODEL : TOYOTA PREVIA 2.4 CVT 7
SEATER

CHASSIS NO : JTEGD54M007145538

ENGINE NO : 2AZ4A73881

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLL1400S

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - LH	1	750.00	750.00 ✓
2 Headlamp nozzle - LH	1	285.00	285.00 7 ✓
3 Headlamp nozzle cover - LH	1	38.00	38.00 ✓
4 Front bumper	1	480.00	480.00 ✓
5 Front bumper side retainer - LH	1	55.00	55.00 ✓
6 Front bumper reinforcement	1	255.00	255.00 ? R
7 Front bumper centre grille	1	120.00	120.00 7
8 Front bumper lower garnish <i>reuse</i>	1	115.00	115.00 7
9 Front bumper fog lamp - LH	1	168.00	168.00 7
10 Front bumper sensor	1	198.00	198.00 ✓
11 Washer tank <i>Resonator</i>	1	125.00	125.00 ✓
			2,589.00
		Add 10%	258.90
			2,847.90
LABOUR			
12 To remove and refit front bumper sensor	1	100.00	100.00 30%
13 To check and rectify wiring system	1	80.00	80.00 20%
14 To panel beat & repair LH front fender, LH front chassis frame, including replacement of parts & align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 200%
15 To putty and spray paint on affected areas	1	1,000.00	1,000.00 200%
			2,180.00
<i>XS 2,000.00</i>			
			594.10
			41.58
			635.68
		TOTAL	S\$ 5,027.90
		ADD GST @ 7%	351.95
		GRAND TOTAL	S\$ 5,379.85

SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED SEVENTY-NINE AND CENTS EIGHTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE