

REPAIR ESTIMATE*

VEHICLE NO SHA3991U

12/05/21

MAKE :

MODEL IONIQ G3

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER <i>D.S</i>			\$459.40
1	REAR BUMPER CENTRE MOULDING <i>500</i>			\$451.25
1	REAR BUMPER REINFORCEMENT <i>11</i>			\$394.80
2	REAR BUMPER STAY LH /RH <i>11</i>		\$138.10	\$276.20
10	REAR BUMPER CLIPS <i>new</i>		\$2.20	\$22.00
1	BOOTLID COVER <i>3000</i>			\$2,480.40
1	BOOTLID H EMBLEM <i>new</i>			\$38.00
1	BOOTLID EMBLEM IONID <i>new</i>			\$31.80
1	BOOTLID EMBLEM HYBRID <i>new</i>			\$24.30
1	BOOTLID LAMP RH <i>11</i>			\$870.40
1	BOOTLID TAIL LAMP RH <i>11</i>			\$794.40
1	REAR FLECTOR RH <i>new</i>			\$41.45
1	REAR BUMPER TOW COVER <i>11</i>			\$98.80
1	RADAR BLIND SPOT RH <i>should</i>			\$1,625.00
2	REAR BUMPER BRACKET RH <i>11</i>			\$55.80
				\$7,664.00
	20.00% DISCOUNTED TOTAL			\$1,532.80
				\$6,131.20
1	REAR BUMPER PROTECTOR <i>new</i>			\$50.00
1	REAR NUMBER PLATE W/HOLDER <i>600</i>			\$55.00
1	REAR REVERSE SENSOR <i>new</i>			\$180.00
				\$285.00
	Labour Charge			
	Panel Beating <i>350</i>		700	\$900.00
	Spray Painting Charge <i>250</i>		750	\$800.00
	Remove/Refix rear upholstery		60	\$90.00
	Diagnose and reset error code		120	\$240.00
	Tuff Kote		30	\$60.00
	Remove/Refix reverse sensor		40	\$60.00
	TOTAL LABOUR		1700	\$2,150.00
	ESTIMATE TOTAL			\$8,566.20
	<i>not authorized</i> <i>14/5/21</i> <i>the photo before painting.</i> <i>H. J. S.</i>			

LINK Auto Consultants hereby notify

the Repairer of the following:

- to resurvey before/after spray painting
- to display damaged part(s) during resurvey

Part prices are subject to confirmation

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

• Third party survey is on a "Without Prejudice" basis

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-5281-6

202

4225-28

marcus chua @ linkauto-consultants

p 1786255-28

TYPE OF C: TP

SURVEY B: LKK/MARCUS

DATE : 12/05/21

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 22.05.2021
Time: 09:09:37
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468581
REGN NO : SHA3991U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 08.04.2020
DATE/TIME IN : 12.05.2021 12:30
ACCIDENT DATE : 12.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	
0004 04-01-0104-0852-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16	
0005 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	50.00	5.00	S.N
0006 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1	180.00	180.00	5.00	S.N
0007 04-01-0104-2270-G	EMBLEM-HYBRID	1	24.30	20.00	19.44	
0008 04-01-0104-2271-G	EMBLEM-IONIQ	1	31.80	20.00	25.44	
0009 04-01-0104-2175-G	SYMBOL MARK-H	1	38.00	20.00	30.40	X
0010 28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1	40.00	2.00-	40.00	ADD / REC
0011 28-01-0103-0005-A	REAR BOOT LOGO CTPL	1	30.00	30.00		ADD / REC
0012 28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1	30.00	30.00		ADD / REC
0013 04-01-0104-2256-G	PANEL ASSY-TAIL GATE#	1	2,480.40	20.00	1,984.32	

4 days

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.05.2021

Time: 09:09:37

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468581
REGN NO : SHA3991U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 08.04.2020
DATE/TIME IN : 12.05.2021 12:3
ACCIDENT DATE : 12.05.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 09-01-0104-2207-G UNIT ASSY-REAR CORNER RAD	1	1,625.00	20.00	1,300.00	✓
0015 04-01-0104-2547-G COVER-RR BUMPER SIDE UNDE	1	108.00	20.00	86.40	
SUB-TOTAL :					4,555.28

JOB NATURE

0000 PB	PANEL BEATING	700.00	
0001 SP	SPRAYPAINT CHARGE	750.00	
0002 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR		60.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.		30.00
0004 20-22	REMOVE/REFIX REVERSE SENSOR		40.00
0005 L	DIAGNOSE/RESET ERROR FAULT CODE		120.00
SUB-TOTAL :			1,700.00