

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number: 63685592

Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

User ID PohSuan

	Section A - Accident Details
Registration Number	SHF39M
Case Reference Number	TAX/05/21/2023
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	ТОУОТА
Model	PRIUS4FL
Name of Driver	LEE YONG GUAN
Type of Accident	Head to Rear
Accident Date and Time	8/5/2021 12:25 PM
Accident Reported Date and Time	10/5/2021 11:05 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110886
Special Instruction to ARC,if	TP /REAR PORTION
Prepared Date and Time	10/5/2021 4:14 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates									
Summary of Repair Estimates									
	Quotation from ARC	Adjusted by Surveyor, if applicable							
Total Labour Cost	\$845.00	\$200.00							
Total Spray Cost	\$1,476.00	\$200.00							
Total Spare Part Cost	\$8,498.02	\$869.03							
Total Other Cost	\$680.00	\$30.00							
TOTAL COST	\$11,499.02	\$1,299.03 (P/P)							
Lump Sum Total	\$0.00	\$0.00							
Number of Repair Days	6.0	2.0							
Prepared / Adjusted By	Tuck Foo Kok	Taufikh (LKK) / AIG							
ARC / Surveyor Sign Off Date	10/05/2021 4:58 PM	11/05/2021 2:53 PM							
Signature	at.								
Remarks		Resurvey before paint, part by part							



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number: 63685592

Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

User ID PohSuan

Section C - Quotation and Accident Invoice Details						
Quotation Number	QN-2105-0277	Invoice Number				
Quotation Date	20.05.2021	Invoice Date				
Invoice Amount		Prepared Date				

Section D - Details of Repair Estimates							
Part 1 - Labour Works							
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable					
TO REPAIR REAR PORTION	\$845.00	\$200.00					
Total Labour	\$845.00	\$200.00					

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO RESPRAY REAR BUMPER	\$378.00	\$200.00		
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00		
TO RESPRAY TAIL GATE	\$378.00	\$0.00		
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00		
TO RESPRAY REAR SPOILER	\$180.00	\$0.00		
TO RESPRAY REAR PANEL	\$180.00	\$0.00		
Total Spray Painting & Panel Beating	\$1,476.00	\$200.00		

Job Scope	Quotation from ARC	Adjusted by Surveyor, if		
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00		
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00		
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00		
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00		
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00		
TO WASH AND VACUUM	\$60.00	\$0.00		
Total Other Costs	\$680.00	\$30.00		

Part	Portion	Stock	Part Name	Quantity	List Price	Discount	Final Price	Estimator	Surveyor
lumber		Number	COVED DD DUMBED ACCV	4.00	(\$)	(%)	(\$)	Approved	Approved
		52159- 47927	COVER, RR BUMPER ASSY	1.00	\$485.60	25.00	\$364.20	Replace	Replace
		52462-	PAD, RR BUMPER, RH & LH ,	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		47020	1						
		52462-	PAD, RR BUMPER, RH & LH ,	2.00	\$4.00	25.00	\$6.00	Replace	Replace
		47030	2					ļ	<u> </u>
		52462- 47130	PAD, RR BUMPER, RH & LH,	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52191-	SEAL, RR BUMPER ARM, RH	2.00	\$11.30	25.00	\$16.95	Replace	Replace
		47030	& LH						
		52161-	CLIPS PIECE, FRT & RR	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		16010	BUMPER						
		52576-	RETAINER, RR BUMPER, LH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given
	+	47060	DETAINED DO DUMBED DU	0.00	# 400.00	0.00	00.00	Dl.	Not Oissue
		52575- 47060	RETAINER, RR BUMPER, RH	0.00	\$132.60	0.00	\$0.00	Replace	Not Given
		52453-	GUARD, RR BUMPER,	1.00	\$374.50	25.00	\$280.88	Replace	Replace
		47900	LOWER						
		52169-	COVER, GUARD RR BUMPER	0.00	\$22.00	0.00	\$0.00	Replace	Check
		47070	LOWER						
		52461- 47070	PAD, RR BUMPER, CTR	3.00	\$11.00	25.00	\$24.75	Replace	Replace
		81910-	REAR BUMPER REFLECTOR	0.00	\$39.00	0.00	\$0.00	Replace	Not Given
		47030	ASSY, REFLEX, RH		00.00		1,0.00		1.131.311011



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/05/2021
User ID PohSuan

lumber otal	Totton	Number	- ac Humo	Quantity	_13τ 1 1106 φ	(%)	(\$)	Check	Check	
dded Sp	Portion		ge After Surveyor Signed off	Quantity	List Price \$	Discount	Final Price	ARC	Surveyor	
otal					\$10,405.50		\$869.03			
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	_x
		58307- 47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$651.00	0.00	\$0.00	Replace	Not Given	x
-		81006- 47030	LAMP SET, STOP CENTER	0.00	\$192.30	0.00	\$0.00	Replace	Not Given	X
		76085- 47916	SPOILER SUB-ASSY, REAR	0.00	\$1,575.40	0.00	\$0.00	Replace	Not Given	$\frac{1}{x}$
			AUTO TAILGATE SYSTEM	0.00	\$2,520.00	0.00	\$0.00	Replace	Not Given	$\frac{1}{x}$
		69321- 47010	TAIL GATE LOCK COVER , BACK DOOR	0.00	\$30.20	0.00	\$0.00	Replace	Not Given	$\exists x > nr$
		69350- 47050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$467.00	0.00	\$0.00	Replace	Not Given	X
		68810- 47061	TAIL GATE BACK DOOR HINGE ASSY, RH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	X
		68810- 47061	TAIL GATE BACK DOOR HINGE ASSY, LH	0.00	\$61.00	0.00	\$0.00	Replace	Not Given	$\frac{1}{x}$
		67005- 47530	TAIL GATE PANEL SUB- ASSY, BACK DOOR	0.00	\$1,147.80	0.00	\$0.00	Replace	Not Given	$\frac{1}{x}$
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	$\exists \hat{x} > nr$
		47200	SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	$ \mathbf{x}$
		75442- 47200	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	0.00	\$54.60	0.00	\$0.00	Replace	Not Given	X
		75441- 47220	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	0.00	\$54.60	0.00	\$0.00	Replace	Not Given	X
		75403- 48010	EMBLEM SUB-ASSY REAR	0.00	\$47.90	0.00	\$0.00	Replace	Not Given	$\frac{1}{x}$
		76801- 47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$913.60	0.00	\$0.00	Replace	Not Given	$\exists x $ \mathbf{n}
		30100	REVERSE SENSOR, REAR BUMPER	0.00	\$180.00	0.00	\$0.00	Replace	Check	$\frac{1}{X}$
		89997-	ANTENNA, ELECTRICAL KEY	0.00	\$72.00	0.00	\$0.00	Replace	Check	X
		47030	UNDER , LH PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	Nec
		47010 58399-	UNDER CENTER COVER, REAR FLOOR	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	$-\frac{x}{x}$
		47050 66259-	UNDER , RH COVER, REAR FLOOR	0.00	\$229.90	0.00	\$0.00	Replace	Check	
		47030 58398-	REINFORCEMENT COVER, REAR FLOOR	0.00	\$175.10	0.00	\$0.00	Replace	Not Given	$\begin{pmatrix} X \\ X \end{pmatrix}$
		47030 52023-	ASSY, REFLEX, LH REAR BUMPER	0.00	\$332.70	0.00	\$0.00	Replace	Check	$-\frac{X}{Y}$

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey beloverater spray pointing
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from insurance Company
Acknowledged by Repairer
Signature:
Date: