



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005810/Uqf3e2	
			Date: 09/06/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 5942K	Veh. Inspected	FBP 1185K	
Policy No.	D20MTPV01008023	Coverage (\$)	0.00	
Claim No.	CMTD2101484/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	14/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB190X	c.c	184	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	LWBPCL1A5J1004013	Colour	RED	
Odometer	44659 KM	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70-17	METZELER	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70-17	METZELER	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/05/2021	Inspection Date	17/05/2021	
Survey held at	XTREME MOTOR TRADING BLK 3006 UBI RD 1 #01-388 SINGAPORE 408700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	