

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA	DATE	: 10/05/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJG3171P		
MODEL	: HONDA CIVIC 1.6		MRH FCS6505T000828
CHASSIS NO			Jasper
<u>ACCIDENT DETAILS</u>		DATE	: 9-May-21
		TIME	: 14:15HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 660.30	\$ 660.30
2	FRONT BUMPER SIDE RETAINER <i>LH Dmg</i>	2	\$ 62.40	\$ 124.80
3	FRONT BUMPER FOGLAMP COVER LH <i>Cut</i>	1	\$ 80.00	\$ 80.00
4	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 322.00	\$ 322.00
5	FRONT BUMPER LOWER GRILLE <i>Not m</i>	1	\$ 160.20	\$ 160.20
6	FRONT BUMPER INNER GARNISH LH <i>Dented</i>	1	\$ 90.00	\$ 90.00
7	CENTRE GRILLE <i>Cut</i>	1	\$ 322.00	\$ 322.00
8	CENTRE GRILLE CHROME <i>Not m</i>	1	\$ 180.30	\$ 180.30
9	CENTRE GRILLE H LOGO <i>Not m</i>	1	\$ 80.00	\$ 80.00
10	HEADLAMP LH <i>cracked</i>	1	\$ 1,120.60	\$ 1,120.60
11	HEADLAMP LOWER BRACKET LH <i>cracked</i>	1	\$ 65.90	\$ 65.90
12	FRONT FENDER LH <i>Not m</i>	1	\$ 580.30	\$ 580.30
13	FRONT FENDER INNER COWLING LH <i>Not m</i>	1	\$ 189.20	\$ 189.20
14	AIR CLEANER BOX ASSY <i>Not m</i>	1	\$ 280.30	\$ 280.30

TOTAL PRICE \$ 4,255.90

LESS 20% \$ 851.18

SUB TOTAL PRICE \$ 3,404.72

2776.20
2220.96

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Ne m</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
3	CENTRE GRILLE CLIP (SET) <i>Ne</i>	1	\$ 20.00	\$ 20.00
4	FRONT FENDER INNER COWLING CLIP (SET) <i>Ne m</i>	1	\$ 20.00	\$ 20.00

40

TOTAL \$ 110.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	200	
3	WIRING CHECK	\$ 60.00	30	
4	TUFF COAT	\$ 250.00	X.	

630

TOTAL \$2,310.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,514.72
TOTAL LABOUR COST : \$ 2,310.00
TOTAL REPAIR COST : \$ 5,824.72

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

Adrian Cj
l/s 11/05/21.

03 Days.

Wheel: 2890 96

L/S: 23K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: