

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21005812/KVF3E2

Date: 29/10/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29146060AL2
Claimant Vehicle No : SJF7530R Insured Vehicle No : SKL6361A
Date of Loss: 10/05/2021 Nature of Claim: TP Claim No: 635876

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJF7530R**
Make & Model: HONDA CIVIC, 2.0 TYPE-R (M) Engine No: K20A5821347
Reg. Date: 10/06/2008 (Man. Year: 2007) Chassis No: FD21401286
Colour: Metallic Grey Odometer: 325110 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R19 Rear Tyre Size: 235/40 R19
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,806.52	4,501.74	7,304.78	61.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	870.00	1,930.00	68.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,606.52	5,371.74	9,234.78	63.22
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	14,606.52	4,100.00	10,506.52	71.93

INSPECTION

Date of Assignment: 14/05/2021
Date Inspected: 18/05/2021 Inspected At: A T Auto Consultant (HQ)
Singapore 680113
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2021)
Parts: 144	HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF7530R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID REFLECTOR RH / LH	O/S Cracked	756.00 FL	*378.00 FL
2	1		*BOOTLID WEATHERSTRIP	Serviceable	236.20 FL	*- FL
3	2		*BOOTLID HINGES RH / LH	Repair	156.80 FL	*- FL
4	2		*BOOTLID HINGES COVER	Serviceable	130.60 FL	*- FL
5	1		*BOOTLID LOCK	Dented	198.10 FL	*198.10 FL
6	1		*REAR BUMPER	Buckled	1,002.80 FL	*717.00 FL
7	2		*REAR BUMPER SIDE BRACKETS RH / LH	Serviceable	130.40 FL	*- FL
8	1		*TAIL LAMP RH / LH	O/S Cracked	1,302.00 FL	*513.70 FL
9	1		*REAR END PANEL	Repair	478.20 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	156.30 FL	*- FL
11	2		*REAR CHASSIS EXTENDER X 4 PCS LH / RH	Repair	396.40 FL	*- FL
12	1		*REAR EXHAUST HOOK	Serviceable	56.20 FL	*- FL
13	1		*EXHAUST HEAT SHIELD REAR	Repair	89.50 FL	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
15	1		*SET REAR REVERSE SENSOR	Dented	320.00 FS	*200.00 FS
16	1		*SET BOOTLID SPOILER MUGEN X 3 PCS	Serviceable	986.30 FS	*- FS
17	1		*SET REAR BUMPER LOWER DIFFUSER MUGEN X 3 PCS	Mtg Cracked	896.30 FS	*896.30 FS
18	1		*BOOTLID CARBON FIBER JAPAN	Cracked	3,896.00 FS	*1,600.00 FS
19	1		*EXHAUST SYSTEM (STOCK) (LOCAL REPAIR)	Dented	1,548.00 FS	*300.00 FS
20	1		*REAR EXHAUST HOOK RUBBER	Serviceable	35.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,831.50	4,863.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,024.98	361.36
Total Parts (\$\$)	11,806.52	4,501.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,200.00	450.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	900.00	400.00
3	WIRING CHARGES	New	100.00	20.00
4	RE-ALIGNMENT OF REAR CHASSIS	New	300.00	0.00
5	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS	New	300.00	0.00
			Gross Labour Cost (\$)	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >