

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-May-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1234 U

1 pc	Front n/s fender <i>Bae</i>	\$	384.00	
1 pc	Front n/s door <i>X Repair</i>	\$	761.00	
1 pc	Rear n/s wheel cover <i>cut</i>	\$	116.00	
		\$	1,261.00	500
	Less 10%	\$	126.10	
		\$	1,134.90	450

S/NETT

1 set	n/s door stickers <i>5 m/c</i>	\$	100.00	
1 pc	Front n/s fender sticker <i>1</i>	\$	60.00	
	Sundry <i>X NN</i>	\$	50.00	
	To check rear n/s wheel alignment	\$	80.00	60
	To dismantle / refit inner components of the front n/s door into new shell door	\$	150.00	X NN
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$	500.00	400
	To putty and spray painting on front n/s door, rear n/s door, front n/s fender	\$	600.00	2500
	To apply rustproofing on the repaired and replaced panels.	\$	150.00	40
		\$	2,824.90	
			1610	
	(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)		-20%: 1250	

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

3 *X Days*
4/5
Gme Qap
17/5/21

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
