

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-May-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1234 U

1 pc	Front n/s fender <i>Bae</i>	\$	384.00
1 pc	Front n/s door <i>X Repair</i>	\$	761.00
1 pc	Rear n/s wheel cover <i>not</i>	\$	116.00
		\$	1,261.00
Less 10%		\$	126.10
		\$	1,134.90

### S/NETT

1 set	n/s door stickers <i>5 m/c</i>	\$	100.00
1 pc	Front n/s fender sticker <i>1</i>	\$	60.00
Sundry <i>X NN</i>		\$	50.00
To check rear n/s wheel alignment		\$	80.00 <i>60</i>
To dismantle / refit inner components of the front n/s door into new shell door		\$	150.00 <i>X NN</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc		\$	500.00 <i>400</i>
To putty and spray painting on front n/s door, rear n/s door, front n/s fender		\$	600.00 <i>= 500</i>
To apply rustproofing on the repaired and replaced panels.		\$	150.00 <i>40</i>
		\$	2,824.90

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

*4 days*  
*4/5*  
*Gme Qap*  
*17/5/21*

<p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul> <p>Acknowledged by Repairer Signature: Date:</p>
---