



南方摩哆 Southern Motor

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

12-May-21
AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore (079120)

Dear Sirs,

RE: Cost of repair to SYM Excel II 150A – FBG7645H

1pc of Front Signal	S\$	65.00
1pc of Brake Lever		35.00
1pc of Handle Bar		85.00
1pc of Body Set		580.00
1pc of Front Mudguard		95.00
1pc of Mirror		65.00
1pc of Exhaust Pipe Cover		180.00
1pc of Side Box		150.00
1pc of Front HeadLamp		380.00
		<hr/> 1,635.00
	Less 10%	163.50
	Nett	<hr/> 1,471.50
	Transport	30.00
	Alignment Fork	65.00
	Rear Givi Box	140.00
	Labor	250.00
		<hr/> <u>\$1,956.50</u>

Yours Faithfully,
Southern Motor



Date: 12 May 2021

Southern Motor
Blk 1006 Bukit Merah Lane 2
#01-10
Singapore 159762

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore 079120

Dear Sirs,

RE: ACCIDENT INVOLING FBG7645H AND YP5663Z ALONG
Queensway ON 06-03-2021 AT 11:00AM

Please be informed that the above-said motorcycle bearing registration no: FBG7645H was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,



Enc.