



南方摩哆 Southern Motor

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

12-May-21

AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore (079120)

Dear Sirs,

RE: Cost of repair to SYM Excel II 150A – FBG7645H

1pc of Front Signal <i>bro /</i>	SS	65.00
1pc of Brake Lever <i>su /</i>		35.00
1pc of Handle Bar <i>? x su</i>		85.00 X
1pc of Body Set <i>su /</i>		580.00
1pc of Front Mudguard <i>su /</i>		95.00
1pc of Mirror <i>su /</i>		65.00
1pc of Exhaust Pipe Cover <i>su /</i>		180.00
1pc of Side Box <i>su /</i>		150.00
1pc of Front HeadLamp <i>? x su</i>	1170	380.00 X

1053
400
1453
200
1162.40

Less 10%

10%
1053
163.50

Nett

1,471.50

Transport

30.00

Alignment Fork

400 { 65.00 30

Rear Givi Box

140.00 *su /*

Labor

250.00 *200*

\$1,956.50

415 - 1,150

Yours Faithfully,
Southern Motor



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene
Hp 90010068

4 days

1/8

12/05/21 @ 1230

Resy after repair