

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email:kentsengcarservices@gmail.com

M/s AIG Asia Pacific Insurance Pte Ltd DATE 18.05.2021
AIG Building, 78 Shenton Way #07-16, CAR NO SLT 5063 M
Singapore 079120 MAKE Toyota Wish

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : GBE 3654 T

Pc	Pcs	JTDCG20W30J008016	UNIT PRICE	AMOUNT	
1	pc	Front bonnet / BT		\$704.10	✓
2	pcs	Front bonnet hinge / BT	\$56.40	\$112.80	✓
1	pc	Front bonnet insulator X NN		\$277.10	X
1	pc	Front bonnet logo / NN		\$66.40	✓
1	pc	Front bonnet bottom lock X NN		\$107.60	X
1	pc	Front bonnet wipper garnish X NN		\$411.90	X
1	pc	Front bonnet wipper garnish (corner) / CA		\$66.70	✓
1	pc	Front head lamp (left) / CA		\$788.60	✓
1	pc	Front support panel assy X repair		\$874.10	X
1	pc	Front grille assy / NN		\$201.10	✓
1	pc	Front grille top garnish X NN		\$177.60	X
1	pc	Front bumper / NN		\$480.10	✓
2	pcs	Front bumper side grille X NN		\$77.10	X
1	pc	Front bumper center grille X NN		\$87.60	X
1	pc	Front bumper inner sponge / CA		\$88.30	✓
1	pc	Front bumper reinforcement X NN		\$279.40	X
2	pcs	Front bumper side bracket X CH - DE		\$68.00	X
2	pcs	Front bumper side retainer X PH X NN		\$68.00	34
1	pc	Front bumper left side fog lamp X NN		\$256.70	X
10	pcs	Front bumper clips / NN	\$5.89	\$58.90	30
1	pc	Front left side fender / NN		\$687.00	✓
1	pc	Front left side fender cowling X		\$112.70	X
8	pcs	Front left side fender cowling clips X NN	\$5.89	\$47.12	X
1	pc	Air cleaner hose X		\$107.60	X
1	pc	Air cleaner box X		\$301.70	X

Handwritten signature

Page 1 of 2 Total

KENT SENG CAR SERVICES.

3259.1

-25%: 2444.32

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email: kentsengcarservices@gmail.com

M/s	AIG Asia Pacific Insurance Pte Ltd	DATE	18.05.2021
	AIG Building, 78 Shenton Way #07-16, Singapore 079120	CAR NO	SLT 5063 M
		MAKE	Toyota Wish

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : GBE 3654 T

Pc	Pcs	JTDGG20W30J008016	UNIT PRICE	AMOUNT
		Continue from page one.		\$6,508.22
		Rust-proofing on the rear accident affected portions.		\$100.00 <i>60</i>
		To check electrical wiring system.		\$80.00 <i>30</i>
		Straightening, repairing and realigning onto front right side fender, cutting front left side fender, cutting front top panel, dismantle & replace the above mentioned parts.		\$1,500.00 <i>500</i>
		Labour for respray front bonnet cover, front top panel, front bumper, front left & right side fender.		\$1,300.00 <i>800</i>
				1390
		<i>5 Days.</i>		
		<i>(Imp Sum Repair)</i>		
		<i>After repair photos.</i>		
		<i>Guo Qiang - 82880282</i>		
		<i>Guo Qiang @ lkkaut.com</i>		
		<i>18/5/21</i>		
				3834.32
				-20%: 3050

[Signature]

KENT SENG CAR SERVICES.

Page 2 of 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: