

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 17 May 2021

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-----------------|
| Vehicle No | : SKF932Z | Accident Date | : 12/05/2021 |
| Make | : AUDI Q5 | Policy No. | : 2100299012-09 |
| Assignment Date | : 16/05/2021 | Excess | : S\$0.00 |
| Date of Inspection | : 14/05/2021 | Est. Duration of Repair | : 0 |
| Inspection At | : PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|------------|
| Repairer's Estimate (Gross) | :S\$ | 39,203.00 |
| Revised Amount | :S\$ | TOTAL LOSS |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 0.00 |

Lump Sum Repair :S\$

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 38,500.00 |
| COE / PARF Rebate | :S\$ | 31,482.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 7,018.00 |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Market value is based on depreciation at \$16K per year