

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0417/2021/TF
DATE : 14-May-21
WIP : 27358

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. JOEHAN TOHKINGKEO
ADDRESS : BLK 251 KIM KEAT LINK
#08-117
SINGAPORE 310251
TELEPHONE : HP +65 97127252
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070176029
VEHICLE NO : **SLL 2512 X**
MODEL CODE : Q3 SPORTBACK 1.4 TFSI S TRONIC
MODEL YEAR : 22/12/2020
ENGINE NO : CZD C20455
CHASSIS NO : WAUZZZF32M1047045
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-May-21
PLACE OF ACCIDENT : ALONG KALLANG WAY INFRONT OF 160 KALLANG WAY



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 2512 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N	TBC	X
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,700.00	✓
4	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$	3,600.00	✓
5	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00 500.	
6	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$	560.00	✓
7	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	✓
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 7,620.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 2512 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$ 400.00 ✓	
9	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$ 200.00 150.	
10	TO REMOVE AND RENEW FRONT WINDSCREEN SENSOR FOIL AND RESET SYSTEM.	S/N \$ 300.00 ✓	
11	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	3250. 3700 88%
12	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH UPPER A-PILLAR AND BOTH FRONT DOORS.	\$ 8,500.00	7 x 550 = 3850 ✓
13	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		\$ 23,804.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 2512 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,815.00	✓ 2251.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 414.00	+
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>cracked</i>	2	\$ 118.00	✓ 93.28
4	FRONT BUMPER CENTER TRIM (MANHATTAN GREY) <i>cracked</i>	1	\$ 356.00	✓ 284.40
5	FRONT BUMPER CENTER GRILLE <i>cracked</i>	1	\$ 317.00	✓ 193.20
6	FRONT BUMPER CENTER SENSOR SUPPORT - LH / RH <i>new</i>	2	\$ 50.00	x
7	FRONT BUMPER CENTER GRILLE COVER <i>new</i>	1	\$ 51.00	x
8	FRONT BUMPER LOWER CLOSING ELEMENT <i>new</i>	1	\$ 190.00	+
9	FRONT BUMPER SPOILER <i>cracked</i>	1	\$ 763.00	✓ 610
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>LH cracked</i>	2	\$ 306.00	153.122
11	FRONT BUMPER AIR GUIDE TRIM - LH / RH (GREY) <i>LH cut</i>	2	\$ 164.00	82.130.80
12	FRONT BUMPER SENSOR SUPPORT - LH / RH <i>new</i>	2	\$ 50.00	? X
13	FRONT RADIATOR GRILLE <i>cracked</i>	1	\$ 1,928.00	✓ 1542.40
14	FRONT RADIATOR GRILLE STRIKER PLATE <i>cracked</i>	1	\$ 244.00	✓ 194.80
15	FRONT RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 56.00	+
16	FRONT RADIATOR GRILLE BRACKET <i>cracked</i>	1	\$ 41.00	2 32.48
17	FRONT RADIATOR GRILLE SECURING PLATE <i>cracked</i>	1	\$ 33.00	2 26.16
18	FRONT RADIATOR GRILLE COVER <i>cracked</i>	1	\$ 244.00	2 194.80
19	FRONT RADIATOR GRILLE CAMERA <i>new</i>	1	\$ 1,141.00	+
20	FRONT BUMPER REINFORCMENT FORM <i>cracked</i>	1	\$ 102.00	✓ 81.60
SUB TOTAL SPARE PARTS			\$ 9,383.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 2512 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT BUMPER REINFORCMENT <i>Best</i>	1	S	916.00 ✓ 732.40
22	FRONT BUMPER GUIDE SECTION - LH / RH <i>crushed</i>	2	S	78.00 ✓ 60.96
23	FRONT BUMPER TOP COVER <i>Crushed</i>	1	S	123.00 ✓ 98
24	CAUTION STICKER <i>3 pcs</i>	1	S	14.00 ✓ 10.88
25	A/C STICKER <i>3 pcs</i>	1	S	8.00 ✓ 5.68
26	HORN - LH / RH <i>Not nee</i>	2	S	137.00 +
27	HORN BRACKET - LH / RH <i>Not nee Best</i>	2	S	✓ 44.00 ✓ 34.08
28	FRONT PARKING AID SENSOR <i>nee</i>	4		TBC +
29	FRONT PARKING AID SENSOR SEAL RING <i>nee</i>	4	S	14.00 +
30	FRONT BUMPER WIRING SET <i>Not cut</i>	1	S	572.00 ✓ 457.60
31	FRONT FENDER - LH / RH <i>Budleed</i>	2	S	2,572.00 ✓ 2057.60
32	FRONT FENDER BRACE - LH / RH <i>Not nee</i>	2	S	176.00 ✓ 49.76
33	FRONT FENDER BRACKET - LH / RH <i>Best</i>	2	S	64.00 ✓
34	FRONT WHEEL HOUSING LINER - LH / RH	2	S	480.00 +
35	FRONT WHEEL HOUSING ATTACHMENT PARTS <i>3 pcs</i>	1	S	101.00 +
36	FRONT WHEEL HOUSING LINER COVER - LH / RH <i>nee</i>	2	S	32.00 +
37	FRONT BONNET <i>Distorted</i>	1	S	3,508.00 ✓ 2806.40
38	FRONT BONNET HINGE - LH / RH <i>Best</i>	2	S	146.00 ✓ 115.52
39	FRONT BONNET ATTACHMENT PARTS <i>nee</i>	1	S	296.00 +
40	FRONT BONNET STRIKER - LH / RH <i>Not nee</i>	2	S	220.00 ?
SUB TOTAL SPARE PARTS			:	\$ 9,501.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 2512 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET SOUND ABSORBER <i>new</i>	1	\$ 219.00	x.
42	FRONT BONNET IMPACT PROTECTION - CENTER <i>new</i>	1	\$ 28.00	✓ 21.84
43	FRONT FENDER TOP COVER - LH / RH <i>new new</i>	2	\$ 82.00	x.
44	FRONT PLENUM CHAMBER COVER <i>new cracked</i>	1	\$ 129.00	✓ 103.20
45	FRONT BONNET BOWDEN CABLE - CENTER <i>Jammed</i>	1	\$ 58.00	✓ 46
46	FRONT BONNET LOCK <i>Damaged</i>	2	\$ 427.00	✓ 341.60
47	FRONT BONNET RELEASE ELEMENT <i>Damaged</i>	1	\$ 58.00	✓ 46
48	FRONT BONNET RELEASE LEVER <i>Not the cut</i>	1	\$ 14.00	✓ 11.20
49	FRONT BONNET RELEASE LEVER COVER <i>new missing</i>	1	\$ 10.00	✓ 7.60
50	FRONT BONNET LOCK CABLE <i>new</i>	1	\$ 74.00	?
51	FRONT HEADLIGHT MOUNTING - LH / RH <i>cracked</i>	2	\$ 236.00	? 188.80
52	FRONT HEADLIGHT - LH / RH <i>Cracked</i>	2	\$ 14,550.00	✓ 11640
53	FRONT HEADLIGHT POWER MODULE - LH / RH <i>new new</i>	2	\$ 1,516.00	? x
54	FRONT HEADLIGHT HEAT SINK - LH / RH <i>Not the</i>	2	\$ 1,957.00	? x
55	FRONT HEADLIGHT HOSE - LH / RH <i>not in</i>	2	\$ 48.00	x.
56	FRONT HEADLIGHT LIFT CYLINDER - LH / RH <i>Cracked</i>	2	\$ 420.00	✓ 335.20
57	FRONT HEADLIGHT LIFT CYLINDER HOSE <i>new</i>	1	\$ 80.00	x.
58	FRONT LOCK CARRIER <i>Cracked</i>	1	\$ 1,272.00	✓ 1017.60
59	FRONT A/C CONDENSER <i>Dented</i>	1	\$ 551.00	✓ 440.80
60	FRONT A/C CONDENSER SEAL <i>new</i>	2	\$ 17.00	✓ 12.80
SUB TOTAL SPARE PARTS			\$ 21,746.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 2512 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	FRONT A/C REFRIGERENT LINE (COMPRESSOR>CONDENSER) <i>cut</i>	1	\$	337.00	✓ 269.60
62	FRONT A/C REFRIGERENT LINE (COMPRESSOR>CUT-OFF POINT)	1	\$	337.00	✓ 269.60
63	FRONT TEMPERATURE SENSOR <i>Best. Coiled</i>	1	\$	7.00	✓ 5.52
64	FRONT ADDITIONAL RADIATOR <i>Bent</i>	1	\$	920.00	✓ 736
65	FRONT RADIATOR <i>Dented.</i>	1	\$	1,035.00	✓ 828
66	COOLANT <i>Nec</i>	6	\$	269.00	✓ 214.56
67	FRONT RADIATOR AIR GUIDE - LH / RH / UPPER / BOTTOM <i>coiled</i>	4	\$	160.00	✓ 125.60
68	FRONT RADIATOR FAN COVER <i>cracked</i>	1	\$	1,529.00	✓ 1223.20
69	FRONT RADIATOR FAN COVER AIR GUIDE <i>cracked</i>	1	\$	56.00	✓ 44.48
70	FRONT INTAKE AIR DUCT COVER <i>coiled</i>	1	\$	29.00	✓ 22.72
71	FRONT INTAKE AIR DUCT COVER AIR GUIDE <i>coiled</i>	1	\$	20.00	✓ 15.36
72	FRONT WATER DRAINAGE HOSE <i>Nec</i>	1	\$	21.00	✓ 16.16
73	FRONT INTAKE AIR DUCT HOSE <i>coiled</i>	1	\$	34.00	✓ 26.80
74	AIR FILTER <i>coiled</i>	1	\$	239.00	✓ 191.20
75	INTAKE MANIFOLD <i>at nec</i>	1	\$	121.00	✗
76	FRONT WHEEL ARCH TRIM - LH / RH <i>Nec</i>	2	\$	1,072.00	✓ 857.60
77	FRONT WINDSCREEN <i>coiled</i>	1	\$	1,294.00	✓ 1035.20
78	FRONT WINDSCREEN RAIN SENSOR GEL FOIL <i>Nec</i>	1	\$	137.00	✓ 109.20
79	FRONT WINDSCREEN RAIN SENSOR RETAINING SPRING <i>Nec</i>	1	\$	21.00	✗
80	FRONT WINDSCREEN WATER DEFLECTOR - LH / RH <i>Nec</i>	2	\$	130.00	✗
SUB TOTAL SPARE PARTS			:	\$ 7,768.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 2512 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
81	FRONT WINDSCREEN PRIMER <i>Neu</i>	1	\$ 20.00	✓ 15.76
82	FRONT DOOR WINDOW SLOT SEAL TRIM - LH / RH <i>Neu</i>	2	\$ 448.00	x,
83	FRONT STEERING AIRBAG	1	\$ 3,165.00	✓ 2532
84	FRONT PASSENGER AIRBAG } Activated	1	\$ 3,165.00	✓ 2532
85	SIDE HEAD AIRBAG UNIT - LH / RH Activated	2	\$ 2,888.00	✓ 2310.40
86	STEERING WHEEL <i>ut</i>	1	\$ 2,241.00	✓ 1792.80
87	DASHBOARD <i>torn</i>	1	\$ 4,575.00	✓ 3660
88	HEADLINER <i>crumpled</i>	1	\$ 2,114.00	✓ 1691.20
89	FRONT LOUD SPEAKER TRIM - RH } <i>not nec</i>	1	\$ 129.00	? x
90	FRONT DEFROSTER NOZZLE - RH	1	\$ 151.00	? x
91	FRONT SEATBELT - LH / RH Activated	2	\$ 1,744.00	✓ 1394.40
92	FRONT SEATBELT HIGH ADJUSTMENT <i>Damaged</i>	2	\$ 342.00	✓ 273.60
93	AIRBAG CONTROL UNIT } Activated	1	\$ 1,642.00	✓ 1313.60
94	AIRBAG CRASH SENSOR	2	TBC	✓ 622.40
95	FRONT GRAB HANDLE - LH / RH <i>ut</i>	2	\$ 215.00	✓ 172
96	REAR GRAB HANDLE - LH / RH <i>ut</i>	2	\$ 216.00	✓ 172
97	A-PILLAR TRIM - LH / RH <i>Behind</i>		\$ 378.00	✓ 301.60
98	B-PILLAR TRIM - LH / RH <i>Neu</i>		\$ 306.00	x
99	C-PILLAR TRIM - LH / RH <i>crushed</i>		\$ 320.00	✓ 255.20
100	DOOR WINDOR - LH <i>Neu</i>		\$ 242.00	x
SUB TOTAL SPARE PARTS			\$ 24,301.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 2512 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
101	FRONT RADIATOR SEALING STRIP <i>New</i>	2	\$ 36.00	<i>X</i>
102	FRONT RADIATOR RUBBER BUSH <i>New.</i>	4	\$ 101.00	<i>2/80.32</i>
103	FRONT NO. PLATE <i>Dented</i>	S/N	\$ 60.00	<i>✓ 60</i>
104	FRONT WINDSCREEN SEALANT <i>New</i>	S/N	\$ 200.00	<i>✓ 200</i>
105	SUNDRIES <i>New</i>		\$ 400.00	<i>? 88'88</i>
TOTAL SPARE PARTS		:	\$ 73,496.00	
TOTAL LABOUR CHARGES		:	\$ 23,804.00	
GRAND TOTAL		:	\$ 97,300.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

❖ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *14/05/21.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, ~~17 Days~~ 28 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to cost market
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be disclosed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
 Date
 Service Advisor
 Pages
 Regn No
 Model No

PA/OD/0417/2021/TF
 20-May-21
 CHANG
 1 of 1
 SLL 2512 X
 AUDI Q3 SPORTBACK 1.4 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	INTAKE MANIFOLD <i>Cruled</i>	\$ 610.00 ✓	538.40
2	CHARGED AIR COOLER <i>Dented</i>	\$ 775.00 ✓	619.60
3	COOLANT HOSE - UPPER <i>cut</i>	\$ 89.00 ✓	71.12
4	REFRIGERANT LINE (A/C CONDENSER -> CUT-OFF POINT) <i>cut</i>	\$ 330.00 ✓	289.20
5	RADIATOR RUBBER BUSH - UPPER <i>Cruled</i>	2 \$ nn 82.00 ✓	
6	RADIATOR BUSH - LOWER <i>new</i>	2 \$ nn 19.00 ✓	
7	GAS FILLED STRUT <i>Damaged</i>	\$ nn 104.00 ✓	20.78
8	REFRIGERANT LINE BRACKET <i>crushed</i>	\$ 27.00 ✓	
9	SPRING BAND CLAMP <i>new</i>	\$ 20.00 ✓	15.52

GRAND TOTAL \$ 2,056.00

For Premium Automobiles Pte Ltd

Adrian Ling
 21/05/21
[Signature]


[Signature]
 Authorised Signature

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate - 2

Daive

CST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0417/2021/TF 27-May-21 CHANG 1 of 1 SLL 2512 X AUDI Q3 SPORTBACK 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	ENGINE OIL END CAP <i>Missing</i>	\$ 23.28 30.00	✓
GRAND TOTAL		\$ 30.00	

For Premium Automobiles Pte Ltd

Adrian Ling
 27/05/21
R.S.



Authorised Signature

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate - 3

Denise

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #C7-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0417/2021/TF
 28-May-21
 CHANG
 1 of 1
 SLL 2512 X
 AUDI Q3 SPORTBACK 1.4 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR SEAT BELT - LH/RH <i>Activated</i>	\$ 1,020.00	✓ 1,020.40
GRAND TOTAL		\$ 1,020.00	

For Premium Automobiles Pte Ltd

Adrian Ling
28/05/21
[Signature]

[Signature]
 Authorised Signature

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate - 4

Derise

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
 Date
 Service Advisor
 Pages
 Regn No
 Model No

PA/OD/0417/2021/TF
 2-Jun-21
 CHANG
 1 of 1
 SLL 2512 X
 AUDI Q3 SPORTBACK 1.4 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO DISMANTLE INTAKE MANIFOLD, INTERCOOLER, AIR COND PIPES AND RENEW ACCORDING TO DAMAGED.	S/N \$ ✓ 980.00	✓
GRAND TOTAL		\$ 980.00	

For Premium Automobiles Pte Ltd

Adrian Ling
[Signature]



Authorized Signature