

**Re: SLN573Y / OD / AIG**

Denise Tay (LKKAuto) &lt;denisetay@lkkauto.com&gt;

Tue 18/5/2021 3:43 PM

**To:** Coco Lu Ting <coco.lu@cyclecarriage.com.sg>**Cc:** Kevin Leong Wai Kit <kevin.leong@cyclecarriage.com.sg>; Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>; SUR <sur@lkkauto.com>

Dear Coco,

In additional,

Labour should be \$750 for 1.5 X \$500.

Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair

*Thanks and regards,**Denise**Case handler**LKK Auto Consultants Pte Ltd**Tel: ☎ 62563561 Fax: 📠 6256 4315**Email: ✉ [sur@lkkauto.com](mailto:sur@lkkauto.com)*

---

**From:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>**Sent:** Tuesday, 18 May 2021 3:40 PM**To:** Coco Lu Ting <coco.lu@cyclecarriage.com.sg>**Cc:** Kevin Leong Wai Kit <kevin.leong@cyclecarriage.com.sg>; Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>; SUR <sur@lkkauto.com>**Subject:** SLN573Y / OD / AIG

Dear Coco,

As instructed by our client , please proceed to repair the **insured vehicle SLN573Y , (Excess \$300)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair*Thanks and regards,**Denise**Case handler**LKK Auto Consultants Pte Ltd**Tel: ☎ 62563561 Fax: 📠 6256 4315**Email: ✉ [sur@lkkauto.com](mailto:sur@lkkauto.com)*