



**CYCLE & CARRIAGE FRANCE PTE. LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



Company Reg No. 200609327M  
 GST Reg No. MR-6500111-X

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
Ong Swee Leong Jeffrey 16 STIRLING RD #30-16 SINGAPORE 148957	Cust No/Name /ONG SWEE LEONG JEFFREY Reg No/Reg Date SLN573Y / 21/04/2017 Date In/Mileage / 0 Chassis No VF73A5GZTGJ808294 Engine No 10FJCC2280823 Make/Model CIT/GC4P 1.6 THP 165 EAT6 INTENSIVE ML Colour/Trim WPP BLANC BANQUISE / IXF YATAGO GREY
Contact No Mobile: 97648491	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	14/05/2021/ 16:15	BLC	442 / CocoLu	16521

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT FENDER RH,				1000.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, SUPPORT PANEL				1140.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				225.00
M SUNDRY Sundry				20.00
M FRONT BUMPER	1.00	1022.00	0.00	1022.00
M BUMPER BRACKET	1.00	327.00	0.00	327.00
M BUMPER MOULDING	1.00	206.00	0.00	206.00
M BUMPER MOULDING	1.00	206.00	0.00	206.00
M BUMPER MOULDING	1.00	225.00	0.00	225.00
M BMPR RUBBR BOOT	1.00	305.00	0.00	305.00
M GUARD GRILLE INFERIEUR	1.00	308.00	0.00	308.00
M BADGE SUPPORT	1.00	203.00	0.00	203.00
M CHEVRON EMBLEM SUPERIEUR	1.00	147.00	0.00	147.00
M CHEVRON EMBLEM INFERIEUR	1.00	147.00	0.00	147.00
M BRACKET SET	1.00	124.00	0.00	124.00
M BRACKET SET LAT	1.00	124.00	0.00	124.00
M BUMPER BRACKET	1.00	511.00	0.00	511.00
M BUMPER BRACKET	1.00	207.00	0.00	207.00
M REAR DUCT RH	1.00	118.00	0.00	118.00
M FACE CROSSMEMBR SUP	1.00	258.00	0.00	258.00
M AIR BULKHEAD RH	1.00	107.00	0.00	107.00
M FRONT WING RH ASS	1.00	566.00	0.00	566.00
M FRONT LIGHT RH	1.00	517.00	0.00	517.00
M HEADLIGHT ASSY RH	1.00	1652.00	0.00	1652.00

Confirm & accepted by	Parts	7,280.00
	Labour	2,415.00
	Standard Menu	0.00
	Specialist Job	0.00
	Diagnostics Job	0.00
	Sundry/Others	20.00
Authorized signatory and company stamp	Total (w/o GST)	9,715.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.