



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005840/Uvf3e2	
			Date: 28/05/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMQ 1650Z	Veh. Inspected	JLC 948	
Policy No.	D21MTPV01005383	Coverage (\$)	0.00	
Claim No.	CMTD2101532/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	17/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA FZ150I	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	PMYKG025080002250	Colour	RED	
Odometer	64679 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80-90-17	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17	MICHELIN	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/05/2021	Inspection Date	17/05/2021	
Survey held at	KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	