

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO21005841/Uqf3n2	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	Date:	17/06/2021	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 1151K	Veh. Inspected	SMD 3696Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2101533/AGC	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	17/05/2021	
2.	. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS PLUS (A)	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	JTDZS3EU60J031374	Colour	GREY	
	Odometer	48056 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
	L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/05/2021	Inspection Date	17/05/2021	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
			<u>E HAVE NOT AUTHORISE</u>	ED REPAIRS.	
5b.		CE TO YOUR INSTRUCTIONS, W	E HAVE NOT AUTHORISE Days of Repair	ED REPAIRS.	