

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Estimate : TP21-042

Date : 11/05/2021
Vehicle Num. : SMN3585G
Make/Model : Honda Shuttle
Chassis/Eng# : GK82002288
Accident Date : 11/05/2021
Claim No. :
Reference :
Policy No. : MT/00822682

Xiao Tony.

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Rear Boot Lid <i>Dented</i>		1,391.80 ✓
2.	1 pc	Rear Boot Lid 'Shuttle' Emblem <i>3Nec</i>		75.00 ✓
3.	1 pc	Rear Boot Lid 'Honda' Emblem		37.80 ✓
4.	1 pc	Rear Boot Lid Weatherstrip <i>new</i>		218.50 +
5.	1 pc	Rear Boot Lid Mechanism Lock <i>new</i>		151.60 +
6.	1 pc	Rear Boot Lid Reflector Lamp LH <i>new</i>		395.40 +
7.	1 pc	Rear Boot Lid Damper LH <i>new</i>		165.00 x.
8.	1 pc	Rear Windscreen Rubber <i>new</i>		218.30 ✓
9.	1 pc	Rear Bumper <i>Defend.</i>		1,350.00
10.	1 pc	Rear Bumper Side Holder LH <i>new</i>		45.90 +
11.	1 pc	Rear Bumper Bracket LH <i>new</i>		48.70 x.
12.	1 pc	Rear Bumper Reflector Lamp LH <i>new</i>		74.50 ✓
13.	1 pc	Rear Bumper Reflector Garnish LH <i>new</i>		64.00 +
14.	1 pc	Rear End Panel <i>Repair</i>		601.50 +
15.	5 pc	Rear Bumper Clips <i>new</i>		24.00 ✓
List TotalS\$:			2772.6	4.80
20.00% Discount S\$:			2218.08	
				4,862.00
				972.40
				3,889.60
SPECIAL NETT ITEMS :				
1.	1 set	Reverse Sensor <i>Damaged</i>	240	380.00 240 ✓
2.	1 pc	Rear Windscreen sealant <i>new</i>		40.00 ✓
Special Nett Total S\$:				420.00
LABOUR :				
To remove, rearrange electrical wirings, check lighting				100.00 <i>30</i>

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120

Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Estimate : TP21-042

Date : 11/05/2021
 Vehicle Num. : SMN3585G
 Make/Model : Honda Shuttle
 Chassis/Eng# : GK82002288
 Accident Date : 11/05/2021
 Claim No. :
 Reference :
 Policy No. : MT/00822682

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		To remove, reinstal rear windscreen		250.00 120
		To remove, reinstal upholstery, inner trim garnishes.		150.00 40
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	1190	1,200.00 400
		To putty and respray painting on affected area.		1,000.00 600
		Labour Total S\$:		2,700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian L
 1/s 14/05/21.
 04 days.

Total: 3648.08
 1/s: 2.9K ✓

Total S\$: 7,009.60
 =====


 SUCCESS UNITED PTE LTD