



APPRAISAL VP PTE LTD

Company Reg No: 201403586G

50 playFair Road #04-01 Noel Building Singapore 367995 | Tel: +65 98511914 | Email: mail@vpappraisal.com

ANNEX A

VEHICLE DAMAGE ASSESSMENT REPORT

Reference No : **VPA-2021/00182**

Vehicle No : **PC8091D**

Workshop : **FTL**

List Item

S/No	Qty	Description	Condition	Repairer's Amount (S\$)	Adjuster's Amount (S\$)
1	1	Rear lh last compartment	Crack	850.00	850.00
Sub Total				850.00	850.00
Less 10%					85.00
Total				850.00	765.00

X R

Special Nett Item

S/No	Qty	Description	Condition	Repairer's Amount (S\$)	Adjuster's Amount (S\$)
Sub Total				0.00	0.00
Total				850.00	765.00



APPRAISAL VP PTE LTD

Company Reg No: 201403586G

50 playFair Road #04-01 Noel Buliding Singapore 367995 | Tel: +65 98511914 | Email: mail@vpappraisal.com

ANNEX B

VEHICLE DAMAGE ASSESSMENT REPORT

Reference No : **VPA-2021/00182**

Vehicle No : **PC8091D**

Workshop **FTL**

Labour Details for front

S/No	Description	Repairer's Amount (S\$)	Adjuster's Amount (S\$)
1	Spray painting	2,400.00	2,200.00
2	Labour charge	900.00	800.00
Total Labour		3,300.00	3,000.00

2000 ✓
500 ✓

ANNEX C

Repair Cost

3 days
part by part

S/No	Description	Repairer's Amount (S\$)	Adjuster's Amount (S\$)
1	Total Part Cost	850.00	765.00
2	Total Repair and Labour Cost	3,300.00	3,000.00
Total Repair Cost		4,150.00	3,765.00

Adjusted Repair Cost

\$3,000.00



APPRAISAL VP PTE LTD

Company Reg No: 201403586G

50 playFair Road #04-01 Noel Bulding Singapore 367995 | Tel: +65 98511914 | Email: mail@vpappraisal.com

VEHICLE DAMAGE ASSESSMENT REPORT

Reference No : **VPA-2021/00182**
Vehicle No : **PC8091D**

ACCIDENT BRIEF

On site survey inspection revealed that the damage noted are consistent with the accident as reported.

Damage at lh rear gille compartment, rear lh panel and etc.

ADVICE

FTL Auto submitted the estimate report cost of \$6,440.00. We have adjusted the repair cost to \$4,956.00. We recommend the repair cost on a Lump Sum of \$3,000.00.

The repairs would require a period of 05 working days.

We are pleased to submit our inspection survey report and photographs for your kind attention.
All survey and inspection work was carried out to the best of our ability, knowledge and experience.

Victor Png
Appraiser
Appraisal VP Pte Ltd

Disclaimer:

This survey was conducted by Appraisal VP Pte Ltd without prejudice basis and we do not authorized repair. Report by Appraisal VP Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle. All findings and recommendations are listed accordingly and final decision of settlement to your good selves. Any disclosure or publications of it or parts thereof shall be the responsibility of such person. No liability shall be attached to Appraisal VP Pte Ltd therefore.