

Navigation icons: back, forward, search, refresh, zoom (100%), print, and a search box with 'Find | Next'.



LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
 TEL: 6256 3561 FAX: 6256 4315
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS3/CTI21005857/R1uf3	
3 ANSON ROAD #16-00		Date: 17/05/2021	
SPRINGLEAF TOWERSINGAPORE 079909		Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	CB 8427D	Veh. Inspected	PC 8091D
Policy No.		Coverage (\$)	0.00
Claim No.	SNM21D202775/C03/THAMYL	Excess (\$)	0.00
Assign From	CRYSTAL LEE	Assign Date	17/05/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/05/2021	Inspection Date	02/06/2021
Survey held at	FTL AUTO 566, WOODLANDS ROAD, SINGAPORE 728697		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			