

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 17-May-21
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMG7045J		
MODEL	: PROTON EXORA 1.6		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 10-Feb-21
		TIME	: 19:45HRS
THIRD PARTY REQUESTOR / CONTACT	:	JACK LI	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Repair</i>	1	\$ 1,050.30	\$ 1,050.30
2	TAILGATE LOGO	1	\$ 68.20	\$ 68.20
3	TAILGATE EMBLEM 'CPS'	1	\$ 55.00	\$ 55.00
4	TAILGATE EMBLEM 'EXORA'	1	\$ 60.00	\$ 60.00
5	TAILGATE LOCK <i>Not Nec</i>	1	\$ 210.00	\$ 210.00
6	TAILGATE WEATHER STRIPE <i>Not Nec</i>	1	\$ 184.10	\$ 184.10
7	TAILGATE WINDSCREEN MOULDING <i>Not Nec</i>	1	\$ 190.50	\$ 190.50
8	REAR BUMPER <i>Deformed</i>	1	\$ 630.00	\$ 630.00
9	REAR BUMPER BEAM <i>Dented</i>	1	\$ 189.00	\$ 189.00
10	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 62.40	\$ 124.80
11	REAR BUMPER REINFORCEMENT BAR <i>Dented</i>	1	\$ 422.20	\$ 422.20
12	REAR BUMPER REINFORCEMENT BAR BRACKET <i>Not on car</i>	1	\$ 90.00	\$ 90.00
13	REAR BUMPER REINFORCEMENT BAR SPONGE	1	\$ 190.00	\$ 190.00
14	REAR END PANEL(OUTER) <i>Repair</i>	1	\$ 450.50	\$ 450.50
15	REAR END PANEL TOP GARNISH <i>Not on car</i>	1	\$ 188.20	\$ 188.20

1830.20

TOTAL PRICE \$ 4,102.80

1647.18

LESS 10% \$ 410.28

SUB TOTAL PRICE \$ 3,692.52

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not in</i>	1	\$ 50.00	\$ 50.00
2	TAILGATE WINDSCREEN SEALANT <i>Not in</i>	1	\$ 100.00	\$ 100.00
3	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
4	REAR END PANEL TOP GARNISH CLIP (SET) <i>ref</i>	1	\$ 20.00	\$ 20.00
5	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 120.00	\$ 120.00
6	REVERSE SENSOR <i>Don't</i>	1	\$ 220.00	\$ 220.00

220

TOTAL \$ 530.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	400	
3	TUFF COAT	\$ 120.00	40	
4	WIRING CHECK	\$ 80.00	30	
5	REMOVE & REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
6	TRANSFER TAILGATE MECHANISM	\$ 80.00	X	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	X	

TOTAL \$2,480.00

920

TOTAL PARTS COST : \$ 4,222.52
 TOTAL LABOUR COST : \$ 2,480.00
 TOTAL REPAIR COST : \$ 6,702.52

Adrian Ly
 17/05/21.
 04 Days.

APPROVED DETAILS

EXCESS :

NO. OF DAYS

RE-SURVEY

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 2787.18

1/5: 2.2K.