## **Performance Motors Limited**



FACSIMILE MESSAGE						
DATE	9 Jun 2021	TIME				
INS	China Taiping	FAX NO				
		NO OF PAGES		<del></del>		
SUV	Rasul			<del></del>		
ATTN	LKK	FAX NO				
MCA	Joseph Yaguel	FAX NO	64743229			
		TEL NO				
		1. 1 1	II CCA TI			
If the fax is not received in order, please do call CSA. Thank you						
Dear S	Sirs,					
Supple	ementary repair for BN	∕1\218i GC				
	e Registration No.	SJD9998Y				
Vehicle Chassis No.		7G26336				
Suppl	ementary Parts to r	eplace YESX Re	efer to attachment			
I- I-	, a same of the sa	NO 🗆				
		МО				

Part / Labour Description *	QTY	Prices
Rear bumper RHS TOP GUID - X (Cracked)	1	\$55.45
Repair RHS tail end panel		\$425.00
Spray paint RHS tail end panel	After Less 5%	\$706.00
Request for additional 1 work day		
	Total =>	\$1,186.45

<sup>\*</sup> All of the above which are highlighted will be considered as agreeable if there i objection and/OR subsequence amendment within 3 work days.