



Final Report

Estimate No. : **b1 58415**
Date Estimated : **14/05/2021**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Tan Kay Siam
63 Almond Crescent

Singapore 677817

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD9998Y	WBA12AK0407G263	28/09/2020	218i Gran Coupe	23

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel and attachment parts.	850.00	0.00	850.00
To respray rear bumper	986.00	0.00	986.00
To check electrical wiring system and lighting at the rear section.	168.00	0.00	168.00
Sundries.	80.00	0.00	80.00
# To replace rear right side panel light assembly	168.00	0.00	168.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER BOTTOM TRIM PANEL (M)	250.20	1.00	0.00	250.20
REAR BUMPER PANEL PRIMED (MSP/PDC/P	1,313.35	1.00	0.00	1,313.35
# RH BUMPER TOP GUIDE	55.45	1.00	0.00	55.45
REAR RH LIGHT IN THE SIDE PANEL	446.00	1.00	0.00	446.00

SUPPLEMENTARY ITEMS

Total Labour :	2,252.00
Total Parts :	2,065.00
Total Labour & Parts :	4,317.00
Deduction for Excess :	
Total Repair Costs less Excess:	4,317.00
GST @7%:	302.19
Grand Total :	4,619.19

LOSS OF USE=\$50 X 3 DAYS
LTA SEARCH FEE=\$7.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 58415**
Date Estimated : **14/05/2021**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Tan Kay Siam
63 Almond Crescent

Singapore 677817

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD9998Y	WBA12AK0407G263	28/09/2020	218i Gran Coupe	23
DESCRIPTION	ORIGINAL PRICE		DISC. %	NETT
To replace rear right side panel light assembly	168.00		0.00	168.00
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH BUMPER TOP GUIDE	55.45	1.00	0.00	55.45
SUPPLEMENTARY ITEMS				
Total Labour :				168.00
Total Parts :				55.45