

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *F8P9568L*
 at Workshop m/s: *BHM*
 of _____
 Insured: *SJQ30545*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: *F8P9568L* Yr Regn: *10/7/19*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: *Yamaha NMAX155* ^{ARS} _{c.c} *155*
 Colour: *Grey* A/C: Insured / Std / NI / NA
 Sp. Reading: *67981* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *MH35G431000011652*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Tyre Size: F: *110/70-13*
 R: *130/70-13*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *TIM SUN*
 Front 6 mm Rear 6 mm
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. *9/5/21* D.O.I. *18/5/21*
 Survey held at _____

Bal. or Market Value: *89500*
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: *1* days Res.: Yes or No
 Lum Sum: *1.3:1* % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS *28PK*
 Date: _____ Person Contacted: *LTA 8 2555*
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
frt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
24/5/21 Conf. found PIP & 420.40 note Raymond

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____

Date/Time, File Return to?
 1) _____
 2) _____

Resurvey No. of Trip: _____ Survey Fee: _____
 Transportation: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : _____
 Lump Sum / I.B.I. (\$) _____)

Survey Fee: _____
Transportation: _____
_____ S + RS. _____ SI
Photos
Others
TOTAL



QUOTATION

Customer :

NO. : 38343

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

*not actual
new
18/5/21
1/1/21 \$
1 day*

DATE : 17/05/2021
CLAIM NO. : 11731
POLICY NO. : MC/00914795
FROM : HASRIANAH

ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

VEHICLE NO. : FBP9568L
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount	
1	BEARING 6300-2NS (NSK) P/N: 69770 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$16.00	32.00	17 X
2	EMBLEM ABS P/N: 63500 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00	11 X
3	HEADLAMP ASSY P/N: 58174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$299.00	299.00	one ✓
4	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	3.00	\$63.00	189.00	100
5	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00	17 X
6	LAMP SIGNAL FRONT RH P/N: 59592 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00	17 X
7	MUDGUARD FRONT (GREY) P/N: 63496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00	one ✓
8	RIM SPORT FRONT(BLACK) P/N: 66875 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$238.00	238.00	11 X
9	SEAL OIL FRONT RIM 20X35X7 P/N: 61482 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00	11 X

*38343 *



S/N	Description	Action	Qty	Unit Price	Amount
10	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00	17 56.00 X
11	VALVE RIM P/N: 57073 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	17 9.00 X
SUB TOTAL					\$956.00
GST @ 7 %					\$66.92
GRAND TOTAL (SGD)					\$1,022.92

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

- LKK / Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*38343 *

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000298K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

NO. : 38377

Supplementary 1 To QTN: 38343

DATE : 20/05/2021
CLAIM NO. : 11731
POLICY NO. : MC/00914795
FROM : RAYMOND

VEHICLE NO. : FBP9568L
MAKE/MODEL : YAM / NMAX155 ABS

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE FRONT WHEEL P/N: 59126	Replace	1.00	\$12.00	12.00
SUB TOTAL					\$12.00
GST @ 7 %					\$0.84
GRAND TOTAL (SGD)					\$12.84

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38377 *

bizSAFE₃



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6201 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2202-1-0383
05/10/11 2:15



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 38343

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 17/05/2021
CLAIM NO. : 11731
POLICY NO. : MC/00914795

FROM : HASRIANAH

VEHICLE NO. : FBP9568L
MAKE/MODEL : YAM / NMAX155 ABS

S/N	Description	Action	Qty	Unit Price	Amount
1	HEADLAMP ASSY P/N: 58174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$299.00 Disc %: 10.00	269.10
2	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$100.00	100.00
3	MUDGUARD FRONT (GREY) P/N: 63496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00 Disc %: 10.00	40.50
4	AXLE FRONT WHEEL P/N: 59126	Replace	1.00	\$12.00 Disc %: 10.00	10.80
SUB TOTAL					\$420.40
GST @ 7 %					\$29.43
GRAND TOTAL (SGD)					\$449.83

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38343 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-10-30
ISO 9001: 2015