



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000		Cust No/Name /Teh Gaik Lean	
		Reg No/Reg Date SLV9469P / 24/01/201	
		Date In/Mileage 17/05/2021/ 0	
		Chassis No KNAFJ411MJ5761784	
		Engine No G4FGHH692158	
		Make/Model KIA/FORTE K3 1.6 A L 189	
		Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	17/05/2021/ 16:15	QUK	282 / Kevin Leong	33459			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000					3	6 X 400		2400 4000.00
	REPLACE FRT BUMPER, FRT LH FENDER , FRT LH DOOR, REAR LH FENDER, REAR BUMPER & AFFECTED AREA							
	REPAIR ON LH ROCKER PANEL, FRT LH A-PILLAR & FRT LH FENDER INNER							
E PNT98000					8	8 X 350		2800 3150.00
	PAINT WORK ON FRT BUMPER, BONNET, FRT LH FENDER, FRT LH DOOR, REAR LH FENDER, REAR BUMPER, LH ROCKER PANEL, FRT LH A-PILLAR & FRT LH FENDER INNER							
E PNT88000								80 120.00
	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR							
E PNT88000								180.00
	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR (photo)							
E PNT88000								140.00
	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR (photo)							
A 13900099								400.00
	TO REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR (photo)							
E PNT88000								120 150.00
	TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL							
A 54900099								30.00
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901								120.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
	USING HI-SCAN PRO TEST							
A WHEELALIGNMENTBP								120.00
	To Conduct Computerize Full Wheel Alignment							
M SUNDAY								30.00
	TO TRANSFER FRT RH RIM INCLUDING BALANCING							
M SUNDAY								260.00
	TO SUPPLY FRT RH TYRE	-						
M SUNDAY								300.00
	TO SUPPLY FRT RH RIM	(UT)						
A 33900099								400.00
	REPLACE FRT UNDERCARRIAGE							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreens in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreens.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
Contact No 64191000

Owner Name & Vehicle Info	
Cust No/Name	/Teh Gaik Lean
Reg No/Reg Date	SLV9469P / 24/01/201
Date In/Mileage	17/05/2021/ 0
Chassis No	KNAFJ411MJ5761784
Engine No	G4FGHH692158
Make/Model	KIA/FORTE K3 1.6 A L 189
Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	17/05/2021/ 16:15	QUK	282 / Kevin Leong	33459			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								✓ 80.00
PERFORM RUST PREVENTION								✓ 80.00
M SUNDRY								30 50.00
TO APPLY SEALANT ON AFFECTED AREA								
M SUNDRY								
SUNDRIES								
M LAMP ASSY-HEAD,LH	BR				1.00	810.00	20.00	648.00
M LAMP ASSY-REAR COMBINATION,LH	BR				1.00	368.00	20.00	294.40
M GEAR ASSY-STEERING					1.00	832.00	20.00	665.60
M KNUCKLE-FRONT AXLE,LH	?				1.00	350.00	20.00	280.00
M HUB ASSY-FR WHEEL	joined				1.00	150.00	20.00	120.00
M BAR ASSY-FR STABILIZER	X				1.00	254.00	20.00	203.20
M LINK-STABILIZER	OT				1.00	72.00	20.00	57.60
M STRUT ASSY-FR,LH	OT				1.00	280.00	20.00	224.00
M PAD-FRONT SPRING,LWR	NPC				1.00	23.00	20.00	18.40
M BEARING-STRUT	NPC				1.00	53.00	20.00	42.40
M INSULATOR ASSY-STRUT					1.00	93.00	20.00	74.40
M PANEL-FENDER,LH	00				1.00	376.00	20.00	300.80
M CARRIER ASSY-FRONT END MODULE	?				1.00	675.00	20.00	540.00
M CROSSMEMBER COMPL	?				1.00	1330.00	20.00	1064.00
M ARM COMPLETE-FR LWR,LH	BT				1.00	380.00	20.00	304.00
M PANEL ASSY-FRONT DOOR,LH	00				1.00	1542.00	20.00	1233.60
M PANEL ASSY-QUARTER OUTER,LH	00				1.00	1213.00	20.00	970.40
M INSULATOR-FENDER LH	NPC				1.00	28.00	20.00	22.40
M COVER-FR BUMPER	BR				1.00	633.00	20.00	506.40
M LIP ASSY-FRONT BUMPER	?				1.00	55.00	20.00	44.00
M DUCT ASSY-AIR CURTAIN,LH	BR				1.00	6.00	20.00	4.80
M AIR DUCT-FR BUMPER,LH	BR				1.00	33.00	20.00	26.40
M COVER-BLANKING FR FOG LH	?				1.00	18.00	20.00	14.40
M ABSORBER-FRONT BUMPER ENERGY	?				1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR	?				1.00	114.00	20.00	91.20
M RAIL ASSY-FR BUMPER	?				1.00	496.00	20.00	396.80
M BRACKET-FR BUMPER SIDE MTG,LH	BR				1.00	13.00	20.00	10.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreens in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreens.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.	MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / Teh Gaik Lean	
		Reg No/Reg Date SLV9469P / 24/01/201	
		Date In/Mileage 17/05/2021/ 0	
		Chassis No KNAFJ411MJ5761784	
		Engine No G4FGHH692158	
		Make/Model KIA/FORTE K3 1.6 A L 189	
		Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/05/2021/ 16:15	QUK	282 / Kevin Leong	33459
Description of Goods / Services					
M GUARD ASSY-FRONT WHEEL,LH ✓ CRU			Qty	Unit Price	Disc% Amount
M COVER-RR BUMPER ✓ DD			1.00	95.00	20.00 76.00
M COVER-RR BUMPER,CTR ✓ CUT			1.00	688.00	20.00 550.40
M BRACKET-RR BUMPER SIDE MTG,LH ?			1.00	315.00	20.00 252.00
M BLACK TAPE-FRT DOOR FRAME UPR, ✓ NPK			1.00	29.00	20.00 23.20
M BLACK TAPE-FR DR RR,LH ✓ NPK ?			1.00	13.00	20.00 10.40
M W/STRIP ASSY-FR DR BELT O/S LH ?			1.00	12.00	20.00 9.60
M W/STRIP ASSY-FR DR SIDE LH ?			1.00	58.00	20.00 46.40
			1.00	122.00	20.00 97.60

Estimate

Steve (LKK) 00-N1 AL

17/5/21

5.00pm

EXPIRES - ?

P/P

My BL Sy
20 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by: Signature:
Date:Nett 18,900.40
7% GST on 18900.40 1323.03

Total Payable 20,223.43

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.