



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 15.05.2021
Emailed : 24.06.2021, 1.45pm
Date Survey : 17.05.2021

VEHICLE NO : SLV 9469 P
MODEL : KIA FORTE K3 1.6 A L
WIP : 33459

Material	:	\$	<u>7,700.00</u>
Labour	:	\$	<u>8,995.00</u>
Sub-Total	:	\$	<u>16,695.00</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>16,395.00</u>
GST 7%	:	\$	<u>1,147.65</u>
Grand Total	:	\$	<u>17,542.65</u>
Finalise By/Date	:		<u>LOI / 24/06/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 18/05/2021	Cust No/Name	/Teh Gaik Lean
	Reg No/Reg Date	SLV9469P / 24/01/2018
	Date In/Mileage	17/05/2021/ 67870
	Chassis/Package	KNAFJ411MJ5761784 /KC17PT
	Engine No	G4FGHH692158
	Make/Model	KIA/FORTE K3 1.6 A L 189
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/06/2021/ 13:41	BLK	260 / AiTing	33459			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, LH FRONT FENDER, LH FRONT DOOR, REAR LH FENDER, REAR BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 2400.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, LH FRONT FENDER, LH FRONT DOOR, LH REAR FENDER, REAR BUMPER, LH SIDE ROCKER PANEL, LH FRONT A PILLAR, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2800.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								✓ 80.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENTS TO FACILITATE REPAIR								✓ 180.00
E PNT88000 REMOVE & INSTALL REAR SEATS TO FACILITATE REPAIR								✓ 140.00
A 13900099 REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR								✓ 400.00
E PNT88000 TRANSFER RH FRONT DOOR ATTACHMENTS TO NEW PANEL								✓ 120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT								✓ 120.00
A 33900099 REPLACE LH FRONT UNDERCARRIAGE PARTS								✓ 400.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 80.00
M SUNDRY APPLY SEALANT ON AFFECTED AREAS								✓ 80.00
M SUNDRY SUNDRIES								✓ 30.00
S SPECIALISTJOB								✓ 260.00

300

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Teh Gaik Lean
18/05/2021	Reg No/Reg Date	SLV9469P / 24/01/2018
	Date In/Mileage	17/05/2021/ 67870
	Chassis/Package	KNAFJ411MJ5761784 /KC17PT
	Engine No	G4FGHH692158
	Make/Model	KIA/FORTE K3 1.6 A L 189
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	24/06/2021/ 13:41	BLK	260 / AiTing	33459				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
SUPPLY LH FRONT SPORTS RIM								800.00	
E	PNT88000	REPAIR LH ROCKER PANEL, & LH FRONT WHEEL HOUSING → Supp.							525.00
E	PNT98000	RESPRAY ON LH ROCKER PANEL, LH FRONT WHEEL HOUSING, LH REAR DOOR → Supp.							200.00
A	10028901	REMOVE & INSTALL FUSE BOX WIRING TO FACILITATE REPAIR → Supp.							200.00
A	35000010	CHECK & BLEED ON BRAKING SYSTEM → Supp.							30.00
S	SPECIALISTJOB	TRANSFER RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING							-300.00
X	EXC	INSURANCE EXCESS							
X	LAMP ASSY-HEAD,LH			1.00	✓	810.00	20.00	648.00	
X	LAMP ASSY-REAR COMBINATION,LH			1.00	✓	368.00	20.00	294.40	
X	KNUCKLE-FRONT AXLE,LH			1.00	?	350.00	20.00	280.00	
X	LINK-STABILIZER			1.00	✓	72.00	20.00	57.60	
X	STRUT ASSY-FR,LH			1.00	✓	280.00	20.00	224.00	
X	PAD-FRONT SPRING,LWR			1.00	✓	23.00	20.00	18.40	
X	INSULATOR ASSY-STRUT			1.00	✓	93.00	20.00	74.40	
X	PANEL-FENDER,LH			1.00	✓	376.00	20.00	300.80	
X	ARM COMPLETE-FR LWR,LH			1.00	✓	380.00	20.00	304.00	
X	PANEL ASSY-FRONT DOOR,LH			1.00	✓	1542.00	20.00	1233.60	
X	PANEL ASSY-QUARTER OUTER,LH			1.00	✓	1213.00	20.00	970.40	
X	INSULATOR-FENDER LH			1.00	✓	28.00	20.00	22.40	
X	COVER-FR BUMPER			1.00	✓	633.00	20.00	506.40	
X	DUCT ASSY-AIR CURTAIN,LH			1.00	✓	6.00	20.00	4.80	
X	AIR DUCT-FR BUMPER,LH			1.00	✓	33.00	20.00	26.40	
X	BRACKET-FR BUMPER SIDE MTG,LH			1.00	✓	13.00	20.00	10.40	
X	GUARD ASSY-FRONT WHEEL,LH			1.00	✓	95.00	20.00	76.00	
X	COVER-RR BUMPER			1.00	✓	688.00	20.00	550.40	
X	COVER-RR BUMPER,CTR			1.00	✓	315.00	20.00	252.00	

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Teh Gaik Lean Reg No/Reg Date SLV9469P / 24/01/2018 Date In/Mileage 17/05/2021/ 67870 Chassis/Package KNAFJ411MJ5761784 /KC17PT Engine No G4FGHH692158 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK
18/05/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	24/06/2021/ 13:41	BLK	260 / AiTing	33459		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	BRACKET-RR BUMPER SIDE MTG,LH	1.00	?	29.00	20.00	23.20	
X	BLACK TAPE-FRT DOOR FRAME UPR,	1.00	✓	13.00	20.00	10.40	
X	BLACK TAPE-FR DR RR,LH	1.00	✓	12.00	20.00	9.60	
X	BEARING-FRONT WHEEL HUB → Supp.	1.00		131.00	20.00	104.80	
X	BEARING-STRUT	1.00	✓	54.00	20.00	43.20	
X	HOSE-BRAKE FRONT,LH	1.00		84.00	20.00	67.20	
X	ORNAMENT-KIA NO.115	1.00		32.00	20.00	25.60	
X	MOUNTING CLIP-REAR COMBI	1.00		5.00	20.00	4.00	
X	CLIP	20.00		2.00	20.00	32.00	
X	HINGE ASSY-REAR DOOR UPPER,RH	1.00		33.00	20.00	26.40	
X	MOUNTING CLIP-REAR COMBI	1.00		5.00	20.00	4.00	
X	LAMP ASSY-SIDE REPEATER,LH	1.00		30.00	20.00	24.00	
X	DUCT ASSY-EXTENSION	1.00		144.00	20.00	115.20	
X	FILM-ANTI CHIPPG LH	1.00		27.00	20.00	21.60	
X	HINGE ASSY-DOOR UPPER,LH	1.00		26.00	20.00	20.80	
X	TUBE-M/CYL TO FRT BRAKE,LH	1.00		46.00	20.00	36.80	
X	MOULDING-REAR WINDOW GLASS	1.00		27.00	20.00	21.60	
X	CROSSMEMBER COMPL	1.00	?	1330.00	20.00	1064.00	
X	HUB ASSY-FR WHEEL	1.00	✓	150.00	20.00	120.00	
X	W/STRIP ASSY-RR DR BELT O/S LH → Supp.	1.00		89.00	20.00	71.20	
Z	TEXT						
	AIG OD CLAIM						
	DOA : 15.05.21						
	SURVEYOR : STEVE LKK						
	POLICY NO : 1800004413-03						

Proforma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	7,700.00	Nett	16,395.00
Labour	8,515.00	7% GST on	1147.65
Standard Menu	0.00		
Specialist Job	290.00	Total Payable	17,542.65
Diagnostics Job	0.00		
Sundry/Others	-110.00		
Total(w/o GST)	16,395.00		



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SLV 9469 P**

	<u>Materials</u>	<u>Cost (\$)</u>
1	Bearing-front wheel hub	131.00
2	Hose-brake front, LH	84.00
3	Ornament-Kia No.115	32.00
4	Mounting Clips	5.00
5	Clips (x20)	40.00
6	Hinge assy-Rear door upper, RH	33.00
7	Mounting Clip-rear combi	5.00
8	Lamp assy-side repeater, LH	30.00
9	Duct assy-extension	144.00
10	Film-Anti Chippg LH	27.00
11	Hinger assy-door upper, LH	26.00
12	Tube-M/Cyl to frt brake, LH	46.00
13	Moulding-Rear window glass	27.00
14	W/strip assy-RR dr belt O/S LH	89.00

Total Materials 719.00

Less 20% discount 143.80

Total after discount 575.20

	<u>Labour</u>	<u>Cost (\$)</u>
1	Repair LH rocker panel, & LH front wheel housing	800.00
2	Respray on LH rocker panel, LH front wheel housing, LH rear door	525.00
3	Remove & install fuse box wiring to facilitate repair	200.00
4	Check & bleed on braking system	200.00


Total labour 1,725.00

Total amount 2,300.20

7% GST 161.01

Grand total \$ 2,461.21

Thank You,
Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SLV 9469P

WIP: 33459

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Fit LH Knuckle Axle	? / SUPP			
2	Bearing wheel	? / SUPP			
3	KIA LOGO	? / SUPP			
4	HINGE ASSY-REAR RODR UPPER LH	? / SUPP			863183R500
5	BRACKET-RR BUMPER	? / SUPP			79410D8000
6	MOUNTING CLIP-REAR COMB	? / SUPP			923031Y000
7	CLIP (X20)	? / SUPP			92485A7000 Steve
8	Repair LH Rocker panel	? / SUPP			8659527500 31/5/21
9	Painting LH Rocker panel	? / SUPP			
10	Paint Assy Extension	? / SUPP			
11	Repair LH wheel housing	? / SUPP			28220A7000
12	Painting LH wheel housing	? / SUPP			Steve 1/6/21
13	RR J Fuse box wiring	? / SUPP			
14	Add oil day - total 23 day	? / SUPP			
15	Hinge Assy - Rear Door upper LH	? / SUPP			RT 793102E200
16	Pint - Anti Chipping LH	? / SUPP			RR 793102E200
17	Moulding - Rear window glass	? / SUPP			RR 8131A7000 530 of 60
18	W Strip Assy - RR RR Belt o/s LH	? / SUPP			83210A7000
19	Painting Rear LH Door	? / SUPP			Steve
20	To check & bleed on brake system	? / SUPP			10/6/21 5127

-0100

MODEL: Forte K3 1.6

SURVEYOR: Steve - Luk

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBOARD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

CAR NO: SLV 9469p

WIP: 33459

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	knuckle - Front Axle, Lt	? / SUPP		/ BT	} Steve 15/6/21
2	wheel Hub Bearing Assy.	? / SUPP		/ H	
3	wheel Hub Assy.	? / SUPP		/ H	
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

MODEL: _____

SURVEYOR: _____

Work Order: R001453
 License: SLV9469P
 Technician: 214 THAM
 Mileage: 67870
 Date: 14.6.21 15:26

15:25pm

Kia : Cerato/Forte : 2013-19 (YD/YDm)

Front : Left				Front : Right		
Actual	Before	Specified Range		Actual	Before	Specified Range
-0°27'	-0°55'	-0°52' 0°08'	Camber	-0°44'	0°22'	-0°52' 0°08'
0°32'	0°12'	3°31' 4°31'	Caster	0°54'	0°50'	3°31' 4°31'
0°01'	-0°27'	-0°03' 0°09'	Toe	0°04'	-0°27'	-0°03' 0°09'
12°15'	12°34'	13°06' 14°06'	SAI	15°14'	14°52'	13°06' 14°06'
11°39'	11°39'	12°14' 14°14'	Included Angle	14°30'	14°30'	12°14' 14°14'
			Turning Angle Diff.			

Front			
	Actual	Before	Specified Range
Cross Camber	0°07'	-0°33'	
Cross Caster	-0°27'	-0°27'	
Cross SAI	-2°58'	-2°18'	
Total Toe	0°05'	-0°54'	-0°06' 0°18'
Cross Turn Diff.			

Rear : Left				Rear : Right		
Actual	Before	Specified Range		Actual	Before	Specified Range
0°12'	-1°30'	-2°00' -1°00'	Camber	-2°05'	-1°45'	-2°00' -1°00'
0°14'	0°14'	0°00' 0°27'	Toe	0°12'	0°15'	0°00' 0°27'

Rear			
	Actual	Before	Specified Range
Cross Camber	0°53'	0°15'	
Total Toe	0°27'	0°27'	0°00' 0°54'
Thrust Angle	0°01'	0°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



CERATO/FORTE../2018/G 1.6 MPI..


VCI



Fault Code Searching

Rescan

Save



System	Status	Result
ENGINE	No Current DTC	Good
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0247

VCI Ver.

02.54

ECU Ver.

M-E-K-01-00-0188

OS Ver.

Android 10