



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Teh Gaik Lean Reg No/Reg Date SLV9469P / 24/01/201 Date In/Mileage 17/05/2021/ 0 Chassis No KNAFJ411MJ5761784 Engine No G4FGHH692158 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	17/05/2021/ 16:15	QUK	282 / Kevin Leong	33459			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E PNT88000	REPLACE FRT' BUMPER, FRT LH' FENDER , FRT LH' DOOR, REAR LH FENDER, REAR' BUMPER & AFFECTED AREA REPAIR ON LH ROCKER PANEL, FRT LH A-PILLAR & FRT LH FENDER INNER				3	6 X 400	2400	4000.00
E PNT98000	PAINT WORK ON FRT' BUMPER, BONNET, FRT LH' FENDER, FRT' LH DOOR, REAR' LH FENDER, REAR, BUMPER, LH, ROCKER PANEL, FRT LH, A-PILLAR & FRT LH FENDER INNER				8	X 350	2800	3150.00
E PNT88000	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR						80	120.00
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR (photo)							180.00
E PNT88000	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR (photo)							140.00
A 13900099	TO REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR (photo)							400.00
E PNT88000	TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL						170	150.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
A WHEELALIGNMENTBP	To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY	TO TRANSFER FRT RH RIM INCLUDING BALANCING							30.00
M SUNDRY	TO SUPPLY FRT RH TYRE						1	260.00
M SUNDRY	TO SUPPLY FRT RH RIM						260	300.00
A 33900099	REPLACE FRT UNDERCARRIAGE							400.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Teh Gaik Lean Reg No/Reg Date SLV9469P / 24/01/201 Date In/Mileage 17/05/2021/ 0 Chassis No KNAFJ411MJ576178A Engine No G4FGHH692158 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	17/05/2021/ 16:15	QUK	282 / Kevin Leong	33459			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								80.00
PERFORM RUST PREVENTION								80.00
M SUNDRY								30 50.00
TO APPLY SEALANT ON AFFECTED AREA								
M SUNDRY								
SUNDRIES					1.00	810.00	20.00	648.00
M LAMP ASSY-HEAD, LH					1.00	368.00	20.00	294.40
M LAMP ASSY-REAR COMBINATION, LH					1.00	832.00	20.00	665.60
M GEAR ASSY-STEERING					1.00	350.00	20.00	280.00
M KNUCKLE-FRONT AXLE, LH					1.00	150.00	20.00	120.00
M HUB ASSY-FR WHEEL					1.00	254.00	20.00	203.20
M BAR ASSY-FR STABILIZER					1.00	72.00	20.00	57.60
M LINK-STABILIZER					1.00	280.00	20.00	224.00
M STRUT ASSY-FR, LH					1.00	23.00	20.00	18.40
M PAD-FRONT SPRING, LWR					1.00	54 53.00	20.00	42.40
M BEARING-STRUT					1.00	93.00	20.00	74.40
M INSULATOR ASSY-STRUT					1.00	376.00	20.00	300.80
M PANEL-FENDER, LH					1.00	675.00	20.00	540.00
M CARRIER ASSY-FRONT END MODULE					1.00	1330.00	20.00	1064.00
M CROSSMEMBER COMPL					1.00	380.00	20.00	304.00
M ARM COMPLETE-FR LWR, LH					1.00	1542.00	20.00	1233.60
M PANEL ASSY-FRONT DOOR, LH					1.00	1213.00	20.00	970.40
M PANEL ASSY-QUARTER OUTER, LH					1.00	28.00	20.00	22.40
M INSULATOR-FENDER LH					1.00	633.00	20.00	506.40
M COVER-FR BUMPER					1.00	55.00	20.00	44.00
M LIP ASSY-FRONT BUMPER					1.00	6.00	20.00	4.80
M DUCT ASSY-AIR CURTAIN, LH					1.00	33.00	20.00	26.40
M AIR DUCT-FR BUMPER, LH					1.00	18.00	20.00	14.40
M COVER-BLANKING FR FOG LH					1.00	84.00	20.00	67.20
M ABSORBER-FRONT BUMPER ENERGY					1.00	114.00	20.00	91.20
M STIFFNER-FR BPR LWR					1.00	496.00	20.00	396.80
M RAIL ASSY-FR BUMPER					1.00	13.00	20.00	10.40
M BRACKET-FR BUMPER SIDE MTG, LH								

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Teh Gaik Lean Reg No/Reg Date SLV9469P / 24/01/201 Date In/Mileage 17/05/2021/ 0 Chassis No KNAFJ411MJ5761784 Engine No G4FGHH692158 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	17/05/2021/ 16:15	QUK	282 / Kevin Leong	33459			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GUARD ASSY-FRONT WHEEL, LH	CRU			1.00	95.00	20.00	76.00
M	COVER-RR BUMPER	RD			1.00	688.00	20.00	550.40
M	COVER-RR BUMPER, CTR	RUI			1.00	315.00	20.00	252.00
M	BRACKET-RR BUMPER SIDE MTG, LH	?	BR		1.00	29.00	20.00	23.20
M	BLACK TAPE-FRT DOOR FRAME UPR,		NR		1.00	13.00	20.00	10.40
M	BLACK TAPE-FR DR RR, LH				1.00	12.00	20.00	9.60
M	W/STRIP ASSY-FR DR BELT O/S LH	?	X	NN	1.00	58.00	20.00	46.40
M	W/STRIP ASSY-FR DR SIDE LH	?	X	MM	1.00	122.00	20.00	97.60

## Estimate

Store (LKK) 00-NM AL

17/5/21

5.00pm

Excess - ?

P/P

My BL Sy

20 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm &amp; accepted by Signature:

Date:

7% GST on      Nett      18,900.40  
18900.40      1323.03  
Total Payable      20,223.43

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.