

Survey
17/5/2021
1220 hrs
TGL in line

Resurvey
18/5/2021
TGL in line
1400 hrs

Resurvey
19/5/2021
1400 hrs
TGL in line

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No: **SMX9175P**
Model and make: Mitsubishi EVO 10 GSR
Chassis No: CZ4A0000602

Qty Spare Parts

- 1 Front bumper
- 1 Front bumper LH side retainer
- 1 Front bumper number plate garnish
- 1 Front bumper LH fog lamp cover
- 1 Front bumper top rubber seal
- 1 Front LH fender
- 1 Front LH fender splash shield
- 1 Front LH fender side garnish
- 1 LH headlamp assy
- 1 Front LH shock absorber
- 1 Front LH lower arm
- 1 Front LH knuckle arm
- 1 Front LH wheel bearing with hub
- 1 Steering rack and pinion
- 1 Front LH tie rod
- 1 Front LH tie rod end ball joint

List Price (\$) 2007

\$ 1050.60	1,424.80	BR✓
\$	59.70	NEC✓
\$ 40.00	82.10	MIS✓
\$	293.00	BR✓
\$	118.00	NDX
\$ 862.00	1,234.00	DD✓
\$ 96.00	229.54	TN✓
\$	164.20	NDX
\$ 1,100.00	1,845.30	BR✓
\$ 680.00	846.00	BT✓
\$	781.00	} NDX
\$	703.00	
\$ 378.00	527.00	JM✓
\$	2,285.00	NDX
\$	138.00	} NDX
\$	78.00	
4,559.30		

4,559.30
@ 10%
455.93
4,103.37

\$	10,808.64
-10%	\$ 1,080.86
\$	9,727.78

Qty Spare Parts

- 1set Front bumper clips
- 1set Front LH fender splash shield clips
- 1 Front number plate
- 1 Front bumper lower carbon fibre spoiler
- 1 Front bumper LH upper carbon fibre canard
- 1 Front bumper LH lower carbon fibre canard
- 1 LH headlamp plastic protector
- 1 LH front sport rim
- 1 LH front tyre
- 1 Brake fluid

Special Nett (\$)

\$ 32.00	80.00	} NEC
\$ 20.00	60.00	
\$ 50.00	70.00	} BR✓
\$ 1000.00	1,450.00	
\$ 150.00	480.00	} NDX
\$ 150.00	480.00	
\$ 60.00	80.00	BR✓
\$	1,000.00	} NDX
\$	450.00	
\$	40.00	NDX

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Company Reg No: 201929175W

Supplementary

Vehicle No:

SMX9175P

Model and make:

Mitsubishi Evo 10

Chassis No:

Qty Spare Parts**List Price (\$)**

- 1 Front bumper LH fog lamp assy
- 1 Front bumper LH fog lamp side grille
- 1 Front bumper LH fog lamp bracket
- 1 Front bumper LH fog lamp garnish

\$	406.00	531.00	BR✓
\$	48.00	73.00	BR✓
\$	NSX	143.00	BR✓
\$	150.00	213.00	BR✓

\$ 960.00

-10% \$ 192.00

\$ 768.00

604.00

@ 10%

60.40

543.60

Resurvey 19/5/2021

14:05 hrs

JGlim M

Total:\$ 768.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 400.00 800.00 ✓

Spray painting on affected panels

\$ 500.00 800.00 ✓

Check wiring and lighting system

\$ 70.00 NNX

Apply rust coating on affected areas

\$ 50.00 NNX

Remove, check, reinstall and replace LH front undercarriage parts to assist repairs

\$ 200.00 320.00 ✓

Conduct, test drive and adjust wheel alignment system

\$ 60.00 100.00 ✓

Conduct and readjust headlamps assy

\$ 50.00 NNX

Towing fee

\$ 50.00 NNX

Total:

\$ 16,757.78

Lump sum repair
Repair days 5

1,160.00

Parts 4,646.97

SN 1,460.00

Labour 1,160.00

7,266.97

@ 20% 1,453.39

5813.58

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

L/S 5,800/- TCRim Min