

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005876/GRS3Q2**Date:** 30/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070016902
Claimant Vehicle No :	SHC7197J	Insured Vehicle No :	SMS2166M
Date of Loss:	12/05/2021	Nature of Claim:	TP
		Claim No:	9622008799SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7197J	Engine No:	D4FDGU706455
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU092493
Reg. Date:	28/07/2016 (Man. Year: 2016)	Odometer:	768792 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,227.04	5,059.36	167.68	3.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,440.00	320.00	18.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,987.04	6,499.36	487.68	6.98
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	6,987.04	5,200.00	1,787.04	25.58
+ GST 7.00/7.00% (S\$)	489.09	364.00	125.09	25.58
Nett Amount (S\$)	7,476.13	5,564.00	1,912.13	25.58
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$114.95/day) (S\$)		574.75		
(S\$)		6,388.75		
Liabile Amount (50.00%) (S\$)		3,194.38		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,196.38		

INSPECTION

Date of Assignment:	17/05/2021	
Date Inspected:	17/05/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cracked	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER GRILLE (RH)	Not Necessary	187.20 FL	*- FL
3	1		*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	22.40 FL	*- FL
4	1		*FRONT BUMPER BRACKET (RH)	Cracked	24.60 FL	*24.60 FL
5	1		*HEADLAMP (RH)	Scratched	1,800.00 FL	*1,800.00 FL
6	1		*FRONT FENDER (RH)	Buckled	663.00 FL	*663.00 FL
7	1		*FRONT FENDER SHIELD (RH)	Deformed	174.90 FL	*174.90 FL
8	1		*FRONT WHEEL CAP RH	Cut	217.20 FL	*217.20 FL
9	1		*FRT SHOCK ABSORBER RH	Bent	684.40 FL	*684.40 FL
10	1		*TIE-ROD END RH	Bent	125.20 FL	*125.20 FL
11	1		*FRT SUSP LOWER ARM RH	Bent	595.90 FL	*595.90 FL
12	1		*FRT KNUCKLE ARM RH	Bent	552.00 FL	*552.00 FL
13	1		*FRT WHEEL HUB RH	Bent	217.20 FL	*217.20 FL
14	1		*FRT S/ABSORBER MTG RH	Bent	217.60 FL	*217.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,533.80	6,324.20
- List Item Discount on L Items 20.00/20.00% (\$)	1,306.76	1,264.84
Total Parts (\$)	5,227.04	5,059.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	560.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	WIRING CHARGE	New	40.00	20.00
4	TUFF KOTE	New	40.00	40.00
5	TOWING FEE	New	60.00	60.00
6	R/I FRT SUSPENSION RH	New	300.00	200.00
7	WHEEL ALIGNMENT	New	120.00	60.00
			Gross Labour Cost (\$\$)	1,760.00
				1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >