

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305 468 755 Via Fax : Email
Date : 150521 (Sat) Your Insured : SMS 2166M
Time of Fax : _____ Date of Acc : 120521

Attn: Motor Claims Department

Ag Asia

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C7197J

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811	} limts@cdge.com.sg Fax no. 6546 8156
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 15.05.21 (Saturday)
 MODEL: Hyundai i40
 VEHICLE NO.: SHC7197J

(LUMP SUM)
 INSURANCE: AIG ASIA
 MVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper Cover	1		\$1,052.20
	Front Bumper Grille (RH)	1		\$187.20
	Front Bumper Bracket Top (RH)	1		\$22.40
	Front Bumper Bracket (RH)	1		\$24.60
	Headlamp (RH)	1		\$1,800.00
	Front Fender (RH)	1		\$663.00
	Front Fender Shield (RH)	1		\$174.90
	Front Wheel Cap RH	1		\$217.20
	SUB TOTAL			\$4,141.50
	LESS 20%			\$828.30
	DISCOUNTED TOTAL			\$3,313.20
	<u>Labour Charge</u>			
	Panel Beating			\$600.00
	Spray Painting Charge			\$600.00
	Wiring Charge			\$40.00
	Tuff Kote			\$40.00
	Towing Fee			\$60.00
	TOTAL LABOUR			\$1,340.00
	ESTIMATE TOTAL			\$4,653.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.