COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA1053R

7/05/2021

MAKE

MODEL IONIO G3

MODEL	IONIQ G3	CHIANG/AIG			
Qty	Parts Description/ Labour	Туре	Unit Price	Amount	
	1 REAR BUMPER / LE	20		\$459.40	✓
	1 REAR BUMPER CENTRE MOULDING	1		\$451.25	\checkmark
	1 REAR BUMPER REINFORCEMENT & BR			\$394.80	/
	-2REAR BUMPER STAY LH /RH │ 렺 LH ✓ BT		\$138.1	\$138.10	\checkmark
	10 REAR BUMPER CLIPS / RH X NN		\$2.2	\$22.00	✓
	1 BOOTLID COVER / Zm			\$2,480.40	✓
	1 BOOTLID H EMBLEM			\$38.00	✓
	1 BOOTLID EMBLEM IONID			\$31.80	/
	1 BOOTLID EMBLEM HYBRID /			\$24.30	/
	1 BOOTLID LAMP LH / SOR			\$870.40	
	1 TAILLAMP LH X NN			\$794.40	
	1 REAR FLECTOR LH X			\$41.45	
	1 REAR BUMPER TOW COVER / WA			\$98.80	/
	1 RADAR BLIND SPOT LH 🧏 NN			\$1,625.00	
	2 REAR BUMPER BRACKET LH 🧘 NN			\$55.80	
				\$7,525.90	5009.2
	20.00%	6		\$1,505.18	
	DISCOUNTED TOTA	4		\$6,020.72	4007.4
	1BOOTLID COMFORT APP STICKER	1 11		\$40.00	
	2BOOTLID COMFORT /TEL NUMBER STICKER /	19mc	\$30.0		I *
	1 REAR NUMBER PALTE W/HOLDER / CAR			\$55.00	l .
	1 REAR REVERSE SENSOR / DM .			\$180.00	
				\$335.00] `
	Labour Charge				
	Panel Beating	1		\$900.00	700
	Spray Painting Charge			\$600.00	
	Towing Fee			\$60.00	I
	Diagnose and reset error code			\$240.00	1
	T ((V))	eulte-t- t		\$60.00	1 - 1
	Remove/Refix reverse sensor the Repairer of	suitants nend f the following	e notify	\$60.00	1 _
	TOTAL CARPINE	after spray p	inting	\$1,920.00	-
	• 10 display dama • Parts prices are	ged part(s) durir	resurvey		1
	ES IN ATE TO TA	y is on a Witho	ut Prejudice" basis	\$8,275.72	1
	Supplementary in the supp	tem(s) must he r	acumunud and		1
	is subject to final	approval from to	Surveyed <u>and</u> Surance Company	5642.4	
	Acknowledged by	1			
	Signature:				
	This is an initial estimate based on a visual inspection of				
	be prepared after the vehicle is surveyed by a motor Sur	veyor appoir	nted by the insurance	company.	J