



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

17 May 2021

Attn: MOTOR CLAIM DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SKV6223M & SMM5968C ON 10/05/2021 @ 15:09 HRS
ALONG KHATIB CAMP CARPARK

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver of the above mentioned vehicle No.: **SKV6223M**

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: **SMM5968C**

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **SKV6223M** and vehicle No.: **SMM5968C** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at: **TONG LUCK AUTO PTE LTD**
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SMM5968C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AIG ASIA PACIFIC INSURANCE PTE. LTD.

ACCIDENT DATE : 10/05/2021

TP VEH REG NO : SMM5968C

ESTIMATE

NO : QUOT202105-000044(00)

DATE : 17/05/2021

POLICY NO : 999995580

VEH REG NO : SKV6223M

MAKE/MODEL : MERCEDES BENZ GLC300
4MATIC COUPE (R19 LED)

CHASSIS NO : W1N2533842F838838

ENGINE NO : 26492080074795

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SKV6223M

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear door - LH	1	2,980.00	2,980.00
2 Rear door weatherstrip - LH	1	328.00	328.00
3 Rear door trimboard rivets -- LH	20	9.00	180.00
4 Rear fender - LH	1	3,970.00	3,970.00
5 Rear wheel arch garnish - LH	1	244.00	244.00
6 Rear wheel arch garnish clips - LH	10	9.00	90.00
			7,792.00
		Less 10%	779.20
			7,012.80
SPECIAL NET			
7 Rear triangle glass selant -- LH	1	40.00	40.00
			40.00
LABOUR			
8 To remove and refit LH rear taingle glass	1	60.00	60.00
9 To transfer LH rear damaged door interior mechanism and glass to new door	1	150.00	150.00
10 To remove and refit LH rear fender interior garnishes and trimboard to facilitates the repairs	1	180.00	180.00
11 To panel beat and striaghten LH rear fender inner panel, LH rear chassis frame, to cut and weld LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
12 To putty and spray on affected areas	1	1,000.00	1,000.00
13 To apply rust proofing on replacement and repaired panels,	1	120.00	120.00
			2,510.00
		TOTAL	S\$ 9,562.80
		ADD GST @ 7%	669.40
		GRAND TOTAL	S\$ 10,232.20

SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED THIRTY-TWO AND CENTS TWENTY ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SMM5968C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AIG ASIA PACIFIC INSURANCE PTE. LTD.

ACCIDENT DATE : 10/05/2021

TP VEH REG NO : SMM5968C

ESTIMATE

NO : QUOT202105-000044(00)

DATE : 17/05/2021

POLICY NO : 999995580

VEH REG NO : **SKV6223M**

MAKE/MODEL : MERCEDES BENZ GLC300
4MATIC COUPE (R19 LED)

CHASSIS NO : W1N2533842F838838

ENGINE NO : 26492080074795

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SKV6223M

Description	Quantity	Unit Price	Amount
		S\$	S\$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE