



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/08 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SMM5968C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AIG ASIA PACIFIC INSURANCE PTE. LTD.

ACCIDENT DATE : 10/05/2021

TP VEH REG NO : SMM5968C

ESTIMATE

NO : QUOT202105-000044(00)

DATE : 17/05/2021

POLICY NO : 999995580

VEH REG NO : SKV6223M

MAKE/MODEL : MERCEDES BENZ GLC300
4MATIC COUPE (R19 LED)

CHASSIS NO : W1N2533842F838838

ENGINE NO : 26492080074795

REG. DATE : 2020

*Not withain
Revery B4 pain*

4-6 day

Estimate Repair Cost to Vehicle No : SKV6223M

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear door - LH	1	2,980.00	2,980.00 ✓
2 Rear door weatherstrip - LH	1	328.00	328.00 ✓
3 Rear door trimboard rivets -- LH	20	9.00	180.00 7
4 Rear fender - LH	1	3,970.00	3,970.00 7
5 Rear wheel arch garnish - LH	1	244.00	244.00 ✓
6 Rear wheel arch garnish clips - LH	10	9.00	90.00 ✓
			7,792.00
		Less 10%	779.20
			7,012.80
SPECIAL NET			
7 Rear triangle glass selant -- LH	1	40.00	40.00
			40.00
LABOUR			
8 To remove and refit LH rear taingle glass	1	60.00	60.00 7
9 To transfer LH rear damaged door interior mechanism and glass to new door	1	150.00	150.00 801
10 To remove and refit LH rear fender interior garnishes and trimboard to facilitates the repairs	1	180.00	180.00 1001
11 To panel beat and straighten LH rear fender inner panel, LH rear chassis frame, to cut and weld LH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 500-7001
12 To putty and spray on affected areas	1	1,000.00	1,000.00 4401
13 To apply rust proofing on replacement and repaired panels	1	120.00	120.00 301
			2,510.00
		TOTAL	S\$ 9,562.80
		ADD GST @ 7%	669.40
		GRAND TOTAL	S\$ 10,232.20

SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED THIRTY TWO AND CENTS TWENTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

date: