

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref

: SKV6223M

Your Ref

SMM5968C

AIG ASIA PACIFIC INSURANCE PTE. LTD.

08 June 2021

78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120

Attn: MOTOR CLAIM DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SKV6223M & SMM5968C ON 10/05/2021 @ 15:09 HRS ALONG KHATIB CAMP CARPARK

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost Of Repair

S\$ 4,801.95

Loss Of Use (\$ 180.00 x 4 days)

S\$ 720.00

GIA / LTA Search

S\$ 7.45

S\$ 5,529.40

Kindly revert within SEVEN days. Filling which we reverse our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08 WESTGATE TOWER SINGAPORE 608531, owner of SKV6223M hereby authorize TONG LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or rental and/or loss of use for our vehicle no.: SKV6223M that was damaged pursuant to the accident which occurred on 10/05/2021 ALONG KHATIB CAMP CARPARK involving vehicle nos: SMM5968C

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 8th day of June 2021

kulini

Signed by third party claimant

TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545
Website: www.tlauto.com.sg
Email: operation@tlauto.com.sg
UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER SINGAPORE 608531

TEL: 6849 8118 FAX:

YOUR REF NO : SMM5968C CLAIM TYPE : THIRD PARTY

ACCIDENT DATE: 10/05/2021 TP VEHICLE NO: SMM5968C NO : AR202106-0024

CLAIM NO : QUOT202105-000044(01)

DATE : 08/06/2021
POLICY NO : 999995580
VEH REG : SKV6223M

MAKE/MODEL: MERCEDES BENZ GLC300

4MATIC COUPE (R19 LED)

CHASIS NO : W1N2533842F838838

ENGINE NO : 26492080074795

REG. DATE : 2020

Final Repair Cost to Vehicle No: SKV6223M

	Description	Quantity	List Price	Amount
			SE	93
	NET PRICE			
1	Rear door - LH	1	2,980.00	2,980.00
2	Rear door weatherstrip - LH	1	328.00	328.00
3	Rear wheel arch garnish - LH	1	244.00	244.00
4	Rear wheel arch garnish clips - LH	10	9.00	90.00
			***	3,642.00
			Less 10%	364.20
			aucon	3,277.80
	SPECIAL NET			
5	Rear door trimboard rivets LH (set)	1	60.00	60.00
-	• •			60.00
	LABOUR			
6	To transfer LH rear damaged door interior mechanism and glass to	1	80.00	80.08
7	new door To remove and refit LH rear fender interior garnishes and trimboard	1	100.00	100.00
	to facilitates the repairs			
8	To panel beat and striaghten LH rear fender inner panel, LH rear chassis frame, to cut and weld LH rear fender, including	1	500.00	500.00
	replacement of parts and align where necessary, to refit and adjust			
	the same			
9	To putty and spray on affected areas	1	440.00	440.00
10	To apply rust proofing on replacement and repaired panels,	1	30.00	30.00
			_	1,150.00
			TOTAL:	S\$4,487.80
			ADD GST @ 7%:	314.15
			GRAND TOTAL:	S\$4,801.95



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Website: www.tlauto.com.sg

Email: operation@tlauto.com.sg UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER

SINGAPORE 608531

TEL: 6849 8118

FAX:

YOUR REF NO : SMM5968C

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE: 10/05/2021 TP VEHICLE NO : SMM5968C

: AR202106-0024 NO

CLAIM NO : QUOT202105-000044(01)

: 08/06/2021 DATE **POLICY NO** : 999995580 **VEH REG** : SKV6223M

MAKE/MODEL: MERCEDES BENZ GLC300

4MATIC COUPE (R19 LED)

CHASIS NO : W1N2533842F838838

ENGINE NO : 26492080074795

REG. DATE : 2020

Final Repair Cost to Vehicle No: SKV6223M

Description Quantity **List Price Amount** <u>S\$</u> SS

TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

E. & O.E.

> Back to OneMotoring



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

17 May 2021 / 13:49:31

Receipt Date/Time: 17 May 2021 / 13:49:31

Tax Invoice/Receipt

Receipt No.: ITNET-00000-210517-001885

Previous Receipt No.:

	em Description/ usiness Transaction Reference o.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)	
Result of Insurance Enquiry - SMM5968C						
As at 10 May 2021/15:09:00						
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.						
	urance Enquiry - SMM5968C					
	quiry Fee		7.00	0.49	7.49	
202	10517134742231111	Cub Tatal	7.00	0.40	7.40	
		Sub-Total	7.00	0.49	7.49	
		Total Before Rounding	7.00	0.49	7.49	
		Rounding Difference			0.04	
		Total Amount Payable			7.45	
		Paid By				
		518834XXXXXX2002	eNETS	Credit Card	7.45	
		Total			7.45	
		Cash Change			0.00	
		Tendered Amount			7.45	
		Excess Refundable Amount			0.00	

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire Vehicle's Insurance Particulars

Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

Vehicle No. SMM5968C	Incident Date/Time 10 May 2021 / 15:09:00	Insurance Company Name AIG ASIA PACIFIC INSURANCE PTE. LTD.
Save as PDF		OK →
Print		